| ASS. REC. BY:  | CS/TP21008975/Kvc  |
|--|--|
| 2420-1   |  |
| The state of the s | SSIGNMENT  |
| From: Date:  | WBA7T22040BM60990  |
| Estimated Cost:  | Type: McCar M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /   |
| OD TP/WS/TP RES/OD RES/EVA/INV/MY  | Truck / Trailer or   |
| To Inspect Vehicle No:   | a -64 '  |
| at Workshop m/s Sta Avto   | Colour M.O. Blue AIC: Insured / Std / NI / NA  |
| of   | Sp.Reading Soul T/Radio: Insured / Std / N1 / NA   |
| Insured:   | Eng/No:  |
| Policy No.   | CNO: WBA 77.22040BM 6099   |
| Claims No.   | Gen. Cond: Qood) Fair / Poor / Burnt   |
| Sum Insured: Excess:   | Steering: Inorder Jammed / Leaked / Burnt or   |
| (Client's Record)  | Brake: Inoxae/Jammed/Leaked/Burnt or   |
| Make of Veh:   | Modi: NII / S/Rim / STO A/Rim or   |
| The state of the s | Tyre Size: F: 245/40R20  |
| (Policy Condition)   | R: 275/35R20   |
| Remark: The veh had commenced its N/S O/S  | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /  |
| repair at the time of inspection.  | TOYO / YOKO or   |
| Bal. or Market Value:  |  |
| IDAC Accident Rport: Consistent? : Yes or No   | R/Bal. S Dood O  |
| GIA / PR Seen: Consistent? : Yes or No   | L/Bal. 9 mm  |
| Est Repairs: days Res.: Yes or No  | D.O.A. / D.O.I. 25/8/202   |
| Lum Sum: % 3 Val.: Yes or No   | Survey held at   |
| CA / REV / REP. / 24 HRS   |  |
| Vehicle: IN / OUT  | Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or   |
| Date:Person Contacted:   | The U/C / Chassis frame / Body Structure affected due to collision.  |
| Date / Time Action / Instruction   | The state of the s |
| Fu LTA purpose -No GIA re  | port, no of of days  |
| 31/8/21 Submit \$2660 (Red 80, 3%)   |  |
| 31/8/21 Submit \$2660 (Red 80, 3%)   |  |
|  |  |
|  |  |
|  |  |
|  |  |
| sta/Timo, File Pase to?  |  |
| . Freii. Report  | Days Of Repair:  |
| ulte/Time, File Return to?   | Resurvey No. of Trip: Survey Fee:  |
| 31/8/21-Typist Add Fee:  | Transporta6/yi:  |
| Aud Fee:   |  |
| aport Format: TP   | : Interview (\$ ); First 35  |
|  | Tech Inys (\$ ) Others   |
| ump Sum / I.B.I: (5  | Weekend (\$  |
|  | TOTAL  |
|  |  |



No.176 Sin Ming Drive, #04-05 Autocare, Singapore 575721 Tel: 6452 5515 Fax: 6452 5595

| Spare Parts    |                        |                  |   |           |
|----------------|------------------------|------------------|---|-----------|
| Vehicle No. :  | TBA                    | Submit By        | : | BRYAN TAN |
| Make & Model : | BMW 740Li M Sport AUTO | Year Manufacture | : | 2019      |
| Chassis No :   | WBA7T22040BM60990      | Engine No.       | : | 11245700  |

11245700

|       | Cost / List  |         |                   |                |                            |  |  |  |
|-------|--|---------|-------------------|----------------|----------------------------|--|--|--|
| S/No. | Part Description   | Qty     | Unit<br>Price     | Price          | Disposition by<br>Surveyor |  |  |  |
| 1     | Used Rear Boot Lid Cover   | 1       | \$400.00          | \$400.00       | -                          |  |  |  |
| 2     | Used Rear-Tail lamp Right Inner CM   | 1       | \$350.00          | \$350.00       | _                          |  |  |  |
| 3     | Used Rear. Tail lamp Right Outer Bn  | 1       | \$300.00          | \$300.00       | -                          |  |  |  |
| 3     | Used Rear Bumper Bulca   | 1       | \$480.00          | \$480.00       |                            |  |  |  |
|       |  | 18      |                   |                | 4                          |  |  |  |
| 1     | ARCO CONTRACTOR CONTRA | ,       |                   |                | 1                          |  |  |  |
|       |  | -       |                   |                |                            |  |  |  |
| 1     |  |         | -                 | \$1,530.00     |                            |  |  |  |
|       |  |         |                   |                |                            |  |  |  |
|       |  |         |                   |                | 1                          |  |  |  |
|       |  |         |                   | the marking of | 1 3 20 1                   |  |  |  |
|       |  |         |                   |                |                            |  |  |  |
|       | *  |         |                   |                |                            |  |  |  |
|       |  | ( 1 1 A | and the second of | 7              |                            |  |  |  |
|       |  |         |                   |                | у.                         |  |  |  |
|       |  |         |                   |                |                            |  |  |  |
|       |  |         |                   |                | 1                          |  |  |  |
|       |  |         | and a few con-    |                |                            |  |  |  |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



No.176 Sin Ming Drive, #04-05 Autocare, Singapore 575721 Tel: 6452 5515 Fax: 6452 5595

| La | b | o | u | r |
|----|---|---|---|---|
|    |   |   |   |   |

| Vehicle No.  | : | TBA                    | TBA Submit By       |  | BRYAN TAN |  |
|--------------|---|------------------------|---------------------|--|-----------|--|
| Make & Model | ; | BMW 740Li M Sport AUTO | Year of Manufacture |  | 2019      |  |

| S/No   | Labour Description  | · · · · · · · · · · · · · · · · · · ·                                    | Esimated                | Adjusted Price |
|--------|---|--|-------------------------|----------------|
| 1      | TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDE   |  |                         |                |
|        | REPAIR AREA. (REAR BUMPER , REAR BOOT LID, REAR TAIL LAMPS)   |  | \$300.00                | ~              |
|        |   |  |                         |                |
| 2      | TO INSTALL FRONT RIGHT HEAD LAMP, TO CHECK W  | IRING  | \$50.00                 | 301            |
|        | TAIL LAMP   |  |                         |                |
| 3      | TO CONDUCT WATER LEAKAGE TESTS TO ENSURE F  | PROPER   |                         |                |
|        | AIR AND SEALING.  |  | \$50.00                 |                |
| 4      | TO RESPRAY ALL REPLACED AND AFFECTED PARTS  | y.*.   | \$750.00                | ~              |
| *      | era a service a |  | \$1,150.00              | - 1            |
|        |   |  | **                      |                |
|        |   |  | ,                       | A selection in |
| 1      | 1   | LKK Auto Consulta<br>the Repairer of the                                 | following:              |                |
|        |   | To resurvey before/aft   | er spray painting       |                |
|        |   | <ul> <li>To display damaged p</li> <li>Parts prices are subje</li> </ul> | art(s) during resurvey  | Grand Harris   |
|        |   | Third party survey is c     No Illegal modification                      | n a "Without Prejudice" | basis          |
| 1      |   | Supplementary item(s)  | ) must be resurveyed at | nd             |
|        | TREATS IN SATERA  | <ul> <li>Supplementary item(s is subject to final appr</li> </ul>        | oval from Insurance Co  | mpany          |
| 1      | and the same of transity to be a set one for a first  | Acknowledged by Repa   | irer                    |                |
| 1      |   | Signature:   |                         |                |
| 1      | the the company of the property of  | Date:  | 37°4                    |                |
| -      |   |  |                         |                |
| $\top$ |   |  |                         | ,              |
|        |   |  |                         |                |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.