



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDK 3683D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CUT	1,450.00	683.40
1	REAR BUMPER SIDE RETAINER	NECESSARY	45.00	37.40
1	REAR BUMPER BRACKET	BROKEN	65.00	17.20
5	REAR BUMPER CLIPS	NECESSARY	40.00	20.00
1	TAILLAMP SEALANT	NOT NECESSARY	50.00	-
2	TAILLAMP CLIPS	NOT NECESSARY	20.00	-
1	TAILLAMP BASE PANEL	NOT DAMAGED	105.80	-
1	REAR FENDER	DENTED	1,350.00	899.10
1	REAR FENDER AIR VENT	NOT DAMAGED	95.00	-
1	REAR FENDER INNER TRIM BOARD	DENTED	295.00	295.00
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	85.00	24.30
1	REAR WINDSCREEN GLASS INNER SEAL	NECESSARY	50.00	30.00
14	REAR WINDSCREEN GLASS CLIPS	NECESSARY	60.00	30.00
1	BOOT LID	NOT DAMAGED	1,285.00	-
1	BOT LID LOCK	NOT DAMAGED	215.00	-
1	BOOT LID WEATHERSTRIP	NOT DAMAGED	110.80	-
1	BOOT LID REFLECTOR	NOT DAMAGED	325.00	-
1	BOOT LID REFLECTOR SEALANT	NOT NECESSARY	35.00	-
1	BOOT LID BADGE	NOT NECESSARY	65.00	-
1	BOOT LID EMBLEM 'CIVIC'	NOT NECESSARY	45.00	-
1	BOOT LID EMBLEM '2.0'	NOT NECESSARY	45.00	-
1	BOOT LID EMBLEM 'I-VTEC'	NOT NECESSARY	45.00	-
	LESS 20% DISCOUNT		-1,176.32	-407.28
			4,705.28	1,629.12
	<u>SPECIAL NETT ITEMS</u>			
1	SPORT RIM (SN)	NOT DAMAGED	800.00	-
1	TIRE (SN)	NOT DAMAGED	700.00	-
			1,500.00	-
	<u>LABOUR</u>			
	TOWING FEES.	NOT NECESSARY	120.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REPAIR AND PANEL BEATING AND REPLACING THE ABOVE MENTIONED PARTS.		1,800.00	800.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	180.00	-
	TO RESPRAY AFFECTED AREAS.		1,600.00	600.00
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT. (BEFORE & AFTER)		180.00	60.00
	TO CHECK WIRING FUNCTIONS & CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	180.00	-
	TO APPLY CERMAINC COATING FOR NEW PAINT.	NOT NECESSARY	1,400.00	-
			5,640.00	1,460.00
GRAND TOTAL			11,845.28	3,089.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS3/ASM21004912/Btce2-1

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.