



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M0389Z

Date: 31st Aug 2021

Our Ref: CS3/ASM21004912/Btce2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Yu Dominic Yishan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SDK 3683D

INSURED VEHICLE: SHC 1869T

ACCIDENT DATE: 15/04/2021

We thank you for your instruction on 26/08/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDK 3683D from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles SDK 3683D and SHC 1869T.
- c) Police Report of Vehicles SDK 3683D.
- d) Final Repair Bill of SDK 3683D from M/s D's Graffiti Concepts Pte Ltd.
- e) Colour damaged vehicle photographs of SDK 3683D.

Pre-Repair Inspection Date : 20/04/2021 at M/s Merlin Motor & Engineering Works, Blk 10 Ang Mo Kio Industrial Park 2A #03-13 AMK Autopoint, Singapore 568047.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDK 3683D
Make & Model	: Honda Civic 2.0L A
Year of Registration	: 2006
Chassis Number	: JHMFD26406S200870
Engine Capacity	: 1998 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.