

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008981/AQCN2**Date:** 27/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00160982000
Claimant Vehicle No :	SJF5946M	Insured Vehicle No :	SJF598S
Date of Loss:	24/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204716/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF5946M	Engine No:	L13A4021710
Make & Model:	HONDA FIT, 1.3 G F-Package Skyroof (A)	Chassis No:	GE61018882
Reg. Date:	04/06/2008 (Man. Year: 2008)	Odometer:	166714 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,703.52	5,171.04	3,532.48	40.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,970.00	1,090.00	26.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,763.52	8,141.04	4,622.48	36.22
Approved Total (Overridden) (\$\$)		6,500.00		
Nett Amount (\$\$)	12,763.52	6,500.00	6,263.52	49.07

INSPECTION

Date of Assignment:	26/08/2021	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Date Inspected:	26/08/2021 Inspected At:	
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2022)
Parts:	144	HONDA FIT 1.3 G F-Package Skyroof (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF5946M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,252.00 FL	*859.00 FL
2	1		*REAR TAILGATE INNER LOCK	Damaged	210.00 FL	*210.00 FL
3	1		*REAR TAILGATE CENTRE GARNISH	Cracked	255.00 FL	*255.00 FL
4	2		*REAR TAILGATE NUMBER PLATE LAMP LH & RH	Not Necessary	242.40 FL	*- FL
5	1		*REAR TAILGATE LOGO	Necessary	95.00 FL	*48.00 FL
6	1		*REAR TAILGATE FIT EMBLEM	Necessary	80.00 FL	*49.00 FL
7	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	285.00 FL	*285.00 FL
8	2		*REAR TAILLAMP LH & RH	Cracked	1,110.00 FL	*418.00 FL
9	1		*REAR TAILLAMP PANEL LH & RH	O/s Dented	568.60 FL	*125.00 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
11	1		*REAR BUMPER	Distorted	813.50 FL	*545.00 FL
12	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	110.00 FL	*110.00 FL
13	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	143.00 FL	*- FL
14	1		*REAR BUMPER SPONGE	Not Necessary	151.00 FL	*- FL
15	1		*REAR BUMPER KEYLESS ANTENNA	Not Necessary	211.00 FL	*- FL
16	1		*REAR END PANEL	Distorted	660.00 FL	*465.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed	217.80 FL	*217.80 FL
18	1		*REAR SPARE TYRE TOP BOARD	Deformed	315.10 FL	*265.00 FL
19	1		*REAR SPARE TYRE SPONGE	Cracked	381.70 FL	*294.00 FL
20	2		*REAR FENDER GARNISH LH & RH	Deformed	771.80 FL	*570.00 FL
21	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
23	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS
25	1		*SET REAR TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*REAR WINDSCREEN SEALANTS	Necessary	100.00 FS	*60.00 FS
27	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
28	1		*REAR EXHAUST SILENCER	Not Necessary	446.00 FL	*- FL
29	1		*REAR TAILGATE WEATHERSTRIP	Cut	152.00 FL	*152.00 FL
30	2		*REAR FENDER INNER SHIELD LH & RH	Deformed	156.00 FL	*156.00 FL
31	1		*REAR SPARE TYRE PANEL	Buckled	737.00 FL	*737.00 FL
32	1		*REAR EXHAUST HEAT SHIELD	Crumpled	78.00 FL	*78.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,616.90	6,363.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,913.38	1,192.76
Total Parts (\$\$)	8,703.52	5,171.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,300.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	1,200.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
5	TO REMOVE & REFIX/REPLACE REAR TRIMS.GARNISH AND FITTING SO AS TO FACILITATE REPAIRS AS REAR COMPARTMENT	New	150.00	80.00
6	TO REMOVE AND REPLACE REVERSE SENSOR AND REAR CAMERA AND CHECK FOR PROPER FUNCTIONS	New	120.00	100.00
7	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	120.00	120.00
8	TO REMOVE REAR BOOT MECHANISM	New	120.00	80.00
Gross Labour Cost (\$\$)			4,060.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >