

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008987/KES3Q2
Date: 25/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900162967
Claimant Vehicle No :	SBW8383Y	Insured Vehicle No :	EP9800E
Date of Loss:	05/08/2021	Nature of Claim:	TP
		Claim No:	6945192738SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBW8383Y	Engine No:	A1410833N20B20A
Make & Model:	BMW 428I, 2.0 Coupe (A)	Chassis No:	WBA4A520X0D571753
Reg. Date:	30/12/2014 (Man. Year: 2014)	Odometer:	62925 km
Colour:	Metallic Beige		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,702.34	5,811.52	2,890.82	33.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	620.00	720.00	53.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,042.34	6,431.52	3,610.82	35.96
Approved Total (Overridden) (S\$)		5,100.00		

Nett Amount (S\$)	10,042.34	5,100.00	4,942.34	49.22
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,407.45		

INSPECTION

Date of Assignment: 26/08/2021

Date Inspected: 30/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Hwa Seng Spray Painting Co (160 SIN MING)
 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,450.00 FL	*1,450.00 FL
2	2		*FRONT BUMPER GRILLE	Cracked	720.00 FL	*257.20 FL
3	1		*FRONT BUMPER SPONGE	Cracked	62.10 FL	*62.10 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	418.60 FL	*- FL
5	1		*FRONT NUMBER PLATE GARNISH	Serviceable	115.00 FL	*- FL
6	2		*HEADLAMP	O/S Cracked / N/S Mtg Cracked	4,260.70 FL	*4,260.70 FL
7	1		*O/S LED MODULE	Dented / Shorted	427.25 FL	*427.25 FL
8	1		*O/S BALLAST	Serviceable	872.20 FL	*- FL
9	1		*O/S DRIVER MODULE	Serviceable	767.55 FL	*- FL
10	1		*O/S HID BULB	Serviceable	424.95 FL	*- FL
11	1		*O/S SIGNAL BULB	Serviceable	59.05 FL	*- FL
12	1		*O/S SIGNAL BULB SOCKET	Serviceable	25.20 FL	*- FL
13	1		*FRONT NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS
					Sub Total (\$\$)	9,662.60
					- List Item Discount on L Items 10.00/10.00% (\$\$)	960.26
					Total Parts (\$\$)	8,702.34
						5,811.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL KNOCKING	New	550.00	250.00
2	SPRAY PAINTING (SPECIAL COLOUR)	New	550.00	250.00
3	WIRE CHECKING	New	80.00	20.00
4	LABOUR TO DO HEADLAMP RESET	New	160.00	100.00
Gross Labour Cost (\$\$)			1,340.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >