

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008989/UGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486532
Claimant Vehicle No :	SMA3200K	Insured Vehicle No :	SJT3173R
Date of Loss:	24/08/2021	Nature of Claim:	TP
		Claim No:	8464435667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3200K	Engine No:	FB20YC81975
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Chassis No:	JF1GT7KL5JG031710
Reg. Date:	02/06/2018 (Man. Year: 2018)	Odometer:	64513 km
Colour:	White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,549.36	2,485.12	64.24	2.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	420.00	470.00	52.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,439.36	2,905.12	534.24	15.53
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	3,439.36	2,000.00	1,439.36	41.85
+ GST 7.00/7.00% (S\$)	240.76	140.00	100.76	41.85
Nett Amount (S\$)	3,680.12	2,140.00	1,540.12	41.85
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,382.00		

INSPECTION

Date of Assignment:	26/08/2021	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	04/10/2021 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	2.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	586.50 FL	*586.20 FL
2	1		*HEADLAMP RH	Scratched / Cracked	2,522.20 FL	*2,520.20 FL
3	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	61.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Not Necessary	17.00 FL	*- FL
5	1		*FRONT FENDER RH(NPA)	Repair	0.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					3,186.70	3,106.40
- List Item Discount on L Items 20.00/20.00% (\$)					637.34	621.28
Total Parts (\$)					2,549.36	2,485.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	400.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	400.00	200.00
3	ANTI-RUST COATING	New	50.00	0.00
4	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			890.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >