

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21008993/Vuce2	
	8 SHENTON WAY AXA TOWERSING		Date	e: 07/09/2021	
	ATTN: LOH CYNTH	HIA	Cod	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 5362Y	Veh. Inspected	FBP 3995B	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03GC7	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	26/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA SNIPER	c.c	150	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MH3UG0740K0152594	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90-17	DIABLO	7 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90-17	DIABLO	7 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.				
5.	5. General Information				
	Accident Date	23/08/2021	Inspect Date / Time	26/08/2021 (04:00 PM)	
	Survey held at GLOBAL MOTOR PTE LTD 53 PAYA UBI INDUSTRIAL #01-12 UBI AVE 1 SINGAPORE 408934				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21008993/Vuce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser