

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21008996/AEA3Q2**Date:** 18/04/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SNA5033B **Insured Vehicle No :** SLM7889X
 Date of Loss: 19/08/2021 Nature of Claim: TP Claim No: MFL2021D0003621

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA5033B**
 Make & Model: BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) Engine No: A3150150N20B20B
 Reg. Date: 31/07/2012 (Man. Year: 2012) Chassis No: WBAXG12050DX48486
 Colour: White Odometer: 140537 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/30 R20 Rear Tyre Size: 275/30 R20
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,734.70	12,530.10	5,204.60	29.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	2,110.00	880.00	29.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,724.70	14,640.10	6,084.60	29.36
Approved Total (Overridden) (S\$)		11,700.00		
(S\$)	20,724.70	11,700.00	9,024.70	43.55
+ GST 7.00/7.00% (S\$)	1,450.73	819.00	631.73	43.55
Nett Amount (S\$)	22,175.43	12,519.00	9,656.43	43.55
+ Car Rental (9.0 x S\$150.00/day) (S\$)		1,350.00		
Nett Liability (S\$)		13,869.00		

INSPECTION

Date of Assignment: 21/08/2021
 Date Inspected: 21/08/2021 Inspected At: J-mart Motor Pte Ltd (HQ)
 Blk 5 Defu Lane 10, #01-578
 Singapore 539186
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

Market Value: \$43,000

LTA Rebate: \$28,333

Nett Value: \$ 14,667

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: 143 BMW 520I 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNA5033B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,276.00 FL	*2,276.00 FL
2	1		*BOOTLID LOCK	Damaged	326.00 FL	*326.00 FL
3	1		*BOOTLID W/STRIP	Cut	245.00 FL	*245.00 FL
4	1		*BOOTLID REFLECTORS	O/S Cut	736.00 FL	*368.00 FL
5	1		*BOOTLID LOGO	Necessary	90.00 FL	*90.00 FL
6	1		*BOOTLID LOCK SWITCH	Not Necessary	170.00 FL	*- FL
7	1		*BOOTLID TRIMBOARD	Not Necessary	564.00 FL	*- FL
8	10		*BOOTLID TRIMBOARD CLIPS	Not Necessary	50.00 FL	*- FL
9	2		*BOOTLID HINGES	Not Necessary	170.00 FL	*- FL
10	2		*REAR NO PLATE LAMP	Not Necessary	190.00 FL	*- FL
11	2		*TAILLAMP	N/S Cut / O/S Cracked	1,228.00 FL	*1,228.00 FL
12	2		*TAILLAMP GARNISH	Cut	352.00 FL	*70.00 FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	200.00 FL	*- FL
14	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	992.00 FL	*496.00 FL
15	2		*REAR BUMPER RETAINER	Necessary	160.00 FL	*160.00 FL
16	1		*REAR BUMPER CENTRE HOLDER	Cracked	180.00 FL	*180.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	896.00 FL	*755.00 FL
18	1		*REAR BUMPER REINFORCEMENT LOWER GARNISH	Cracked	197.00 FL	*197.00 FL
19	1		*REAR BUMPER LOWER GARNISH	Cracked	262.00 FL	*262.00 FL
20	1		*BOOTLID LOCK SENSOR WIRE	Damaged	220.00 FL	*220.00 FL
21	1		*BOOTLID LOCK SENSOR ECU	Not Necessary	880.00 FL	*- FL
22	1		*END PANEL	Dented	1,236.00 FL	*964.00 FL
23	1		*END PANEL INNER GARNISH	Cracked	376.00 FL	*376.00 FL
24	1		*EXHAUST PIPE	Damaged	1,263.00 FL	*1,263.00 FL
25	1		*SPARE TYRE CARDBOARD	Deformed	562.00 FL	*351.00 FL
26	1		*REAR BUMPER TOW HOOK COVER	Missing	62.00 FL	*62.00 FL
27	1		*REAR BUMPER	Distorted	3,000.00 FS	*2,000.00 FS
28	1		*REAR BUMPER DIFFUSER	Distorted	1,500.00 FS	*1,200.00 FS
29	1		*REAR BUMPER STICKER	Necessary	200.00 FS	*80.00 FS
30	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
31	2		*EXHAUST PIPE CHROME	Bent	500.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,123.00 13,519.00
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,388.30 988.90

Total Parts (\$\$) 17,734.70 12,530.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	1,000.00
2	SPRAY PAINTING	New	1,400.00	1,000.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	80.00
5	REMOVE & REFIT EXHAUST PIPE	New	80.00	0.00
Gross Labour Cost (\$)			2,990.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >