

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008998/BPA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210055898
Claimant Vehicle No :	SMY9607E	Insured Vehicle No :	SDY505G
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	0194593681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY9607E	Engine No:	28291480440479
Make & Model:	MERCEDES-BENZ GLA200 SPORT, 1.3 (A)	Chassis No:	W1N2477872J170365
Reg. Date:	01/04/2021 (Man. Year: 2020)	Odometer:	5281 km
Colour:	Black		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,085.23	11,064.88	14,020.35	55.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,010.00	3,140.00	60.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,235.23	13,074.88	17,160.35	56.76
Approved Total (Overridden) (S\$)		13,074.00		
(S\$)	30,235.23	13,074.00	17,161.23	56.76
+ GST 7.00/7.00% (S\$)	2,116.47	915.18	1,201.29	56.76
Nett Amount (S\$)	32,351.70	13,989.18	18,362.52	56.76
+ Loss of Use (10.0 x S\$80.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,796.63		
Global Sum Settlement (S\$)		14,790.00		

INSPECTION

Date of Assignment:	26/08/2021	
Date Inspected:	27/08/2021	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	7.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	3,186.30 FL	*2,986.39 FL
2	1		*TAILGATE LOGO	Necessary	110.00 FL	*92.00 FL
3	1		*TAILGATE EMBLEM GLA 200	Necessary	198.00 FL	*135.00 FL
4	1		*TAILGATE INNER LOCK	Jammed	482.30 FL	*294.95 FL
5	1		*TAILGATE INNER LOCK STRICKER	Not Damaged	110.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Damaged	498.00 FL	*- FL
7	2		*TAILGATE LAMP	Broken	1,579.20 FL	*1,440.00 FL
8	1		*TAILGATE INNER TRIM BOARD	Not Damaged	746.20 FL	*- FL
9	1		*TAILGATE REVERSE CAMERA	Not Damaged	620.00 FL	*- FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	314.55 FL	*314.55 FL
11	1		*REAR BUMPER	Broken	1,858.00 FL	*1,350.00 FL
12	1		*REAR BUMPER LOWER	Cut	983.35 FL	*775.00 FL
13	1		*REAR BUMPER CHROME DIFUSSER	No such part	879.20 FL	*- FL
14	1		*REAR BUMPER OUTER CHROME GARNISH	Broken	441.60 FL	*441.60 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	571.20 FL	*300.00 FL
16	1		*REAR BUMPER INNER SPONGE	No such part	325.60 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	851.33 FL	*795.00 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET	No such part	304.00 FL	*- FL
19	2		*REAR BUMPER BRACKET	No such part	291.64 FL	*- FL
20	2		*REAR BUMPER REFLECTOR	Broken	396.00 FL	*130.00 FL
21	1		*REAR BUMPER CENTRE BEAM	Broken	383.00 FL	*230.00 FL
22	1		*REAR BUMPER LOWER CENTRE COVER	No such part	428.79 FL	*- FL
23	4		*REAR BUMPER REVERSE SENSOR	Scratched (2 PCS ONLY)	983.20 FL	*491.60 FL
24	1		*REAR END PANEL	Repair	2,136.60 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH	Not Damaged	425.75 FL	*- FL
26	2		*TAILLAMP	Broken	2,196.00 FL	*2,196.00 FL
27	2		*TAILLAMP LOWER BRACKET	Not Damaged	396.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Damaged	3,600.00 FL	*- FL
29	2		*REAR EXHAUST PIPE HEATSHIELD	Not Damaged	672.00 FL	*- FL
30	1		*REAR EXHAUST PIPE COVER	Not Damaged	358.00 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
36	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
38	1		*REAR BUMPER LOWER CLIPS	Not Necessary	60.00 FS	*- FS
39	1		*REAR BUMPER CHROME DIFUSSER CLIPS	Not Necessary	60.00 FS	*- FS
40	1		*REAR BUMPER OUTER CHROME GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
41	4		*REAR BUMPER REVERSE SENSOR SEAL	Not Necessary	192.00 FS	*- FS
42	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
44	2		*TAILLAMP SEAL	Necessary	120.00 FS	*40.00 FS
45	2		*TAILLAMP CLIPS	No such part	120.00 FS	*- FS
46	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,717.81	12,262.09
- List Item Discount on L Items 10.00/10.00% (\$)	2,632.58	1,197.21
Total Parts (\$)	25,085.23	11,064.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REAR EXHAUST PIPE	New	150.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	100.00	30.00
7	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
8	PANEL BEATING	New	1,800.00	1,000.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,800.00	600.00
Gross Labour Cost (\$\$)			5,150.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >