

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21009001/AES3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	GBE4381Z	<b>Insured Vehicle No :</b>	SLV2127Y
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003751

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE4381Z</b>		
Make & Model:	NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)	Engine No:	K9KC400D054928
Reg. Date:	03/12/2015 (Man. Year: 2015)	Chassis No:	VSKYBAM20Z0115473
Colour:	Grey	Odometer:	250965 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,736.80	3,342.18	4,394.62	56.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,340.00	1,220.00	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,296.80</b>	<b>4,682.18</b>	<b>5,614.62</b>	<b>54.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>(S\$)</b>	10,296.80	3,700.00	6,596.80	64.07
<b>+ GST 7.00/7.00% (S\$)</b>	720.78	259.00	461.78	64.07
<b>Nett Amount (S\$)</b>	<b>11,017.58</b>	<b>3,959.00</b>	<b>7,058.58</b>	<b>64.07</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		535.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		100.00		
<b>Nett Liability (S\$)</b>		<b>4,601.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,600.00</b>		

INSPECTION

Date of Assignment:	26/08/2021	N-51 Automotive Pte Ltd (HQ)
Date Inspected:	26/08/2021 Inspected At:	BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
		AUTOHUB
		Singapore 417921
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Dec 2021)		
<b>Parts:</b>	N/A	NISSAN NV200 1.5 L MT ABS AIRBAG 2WD 6DR (M) (Model not available in database)	
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE4381Z)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR AXLE	Not Necessary	1,997.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	485.90 FL	*485.90 FL
3	1		*REAR BUMPER SIDE RETAINER L/R	O/S Cracked	74.40 FL	*37.20 FL
4	1		*REAR RH FENDER	Dented	1,636.10 FL	*1,636.10 FL
5	1		*REAR RH FENDER INNER AIR VENT	Cracked	78.30 FL	*78.30 FL
6	1		*REAR RH SHOCK ABSORBER	Not Necessary	88.40 FL	*- FL
7	1		*REAR RH SLIDING DOOR	Repair	919.90 FL	*- FL
8	1		*REAR RH TAILGATE DCI EMBLEM	Not Necessary	42.10 FL	*- FL
9	1		*REAR RH TAILGATE HINGE (LOWER)	Not Necessary	49.80 FL	*- FL
10	1		*REAR RH TAILLAMP	Cracked	262.10 FL	*262.10 FL
11	1		*REAR RH WHEEL BEARING	Damaged	794.00 FL	*412.00 FL
12	1		*REAR RH WHEEL RIM	Not Necessary	305.40 FL	*- FL
13	1		*REAR RH WHEEL RIM HUB CAP	Cut	168.60 FL	*168.60 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*REAR RH FENDER STICKER	Necessary	450.00 FS	*280.00 FS
16	1		*REAR RH SLIDING DOOR STICKER	Necessary	350.00 FS	*250.00 FS
17	1		*REAR RH TAILGATE 3D STICKER	Not Necessary	350.00 FS	*- FS
18	1		*SET REAR RH TAILLAMP CLIPS	Necessary	25.00 FS	*10.00 FS
19	1		*REAR RH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,427.00</b>	<b>3,650.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	690.20	308.02
<b>Total Parts (\$)</b>	<b>7,736.80</b>	<b>3,342.18</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE,DAMAGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM, KNUCKLE AR, WHEEL BEARING ,BEARING HUB AND ETC	New	300.00	80.00
3	TO ROAD TEST DRIVING CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
5	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	400.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE -ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
7	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,560.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >