

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009008/AGA3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210042163
Claimant Vehicle No :	SKZ8769X	Insured Vehicle No :	SNA3118D
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	5666732467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8769X	Engine No:	3A92UCT9805
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AFH018870
Reg. Date:	11/02/2016 (Man. Year: 2015)	Odometer:	14961 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,760.40	3,999.50	1,760.90	30.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	2,680.00	1,950.00	42.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,390.40	6,679.50	3,710.90	35.71
Approved Total (Overridden) (S\$)		5,350.00		

(S\$)	10,390.40	5,350.00	5,040.40	48.51
+ GST 7.00/7.00% (S\$)	727.33	374.50	352.83	48.51
Nett Amount (S\$)	11,117.73	5,724.50	5,393.23	48.51
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,176.50		

INSPECTION

Date of Assignment: 26/08/2021

Date Inspected: 26/08/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	708.00 FL	*708.00 FL
2	1		*REAR BUMPER SIDE HOLDER-RH	Damaged	34.00 FL	*34.00 FL
3	1		*REAR BUMPER INNER AIR GUIDE -RH	Cracked	48.00 FL	*48.00 FL
4	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	32.00 FL	*- FL
5	1		*REAR END PANEL	Repair	449.00 FL	*- FL
6	1		*TAIL LAMP -RH	Cut	276.00 FL	*276.00 FL
7	1		*REAR FENDER -RH	Distorted	798.00 FL	*798.00 FL
8	1		*REAR FENDER INNER SHIELD -RH	Torn	98.00 FL	*98.00 FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	105.00 FL	*105.00 FL
10	1		*FRONT BUMPER	Deformed	706.00 FL	*706.00 FL
11	1		*FRONT BUMPER SIDE HOLDER-RH	Damaged	38.00 FL	*38.00 FL
12	1		*FRONT BUMPER FOG LAMP-RH	Not Necessary	263.00 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP COVER-RH	Not Necessary	119.00 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP CHROME MOULDING-RH	Cut	115.00 FL	*115.00 FL
15	1		*HEAD LAMP -RH	Cracked	755.00 FL	*755.00 FL
16	1		*FRONT FENDER-RH	Repair	538.00 FL	*- FL
17	1		*FRONT FENDER EMBLEM -RH	Necessary	74.00 FL	*74.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
20	1		*REAR FENDER INNER SHIELD CLIPS -RH	Necessary	20.00 FS	*20.00 FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
22	1		*REAR WHEEL RIM -RH	Cut	700.00 FS	*480.00 FS
23	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,276.00	4,375.00
- List Item Discount on L Items 10.00/10.00% (\$)	515.60	375.50
Total Parts (\$)	5,760.40	3,999.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,400.00	700.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	50.00
4	TO REMOVE REVERSE SENSOR	New	100.00	30.00
5	TO SPRAY TUFF COAT	New	150.00	60.00
6	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
9	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	600.00	350.00
10	TO PUTTY & SPRAY UP PAINT WORKS	New	600.00	400.00
11	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			4,630.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >