

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009011/R1EA3Q2
Date: 20/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJD7192T	Insured Vehicle No :	SLP8941E
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003665

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD7192T		
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Engine No:	F8351376B38B15A
Reg. Date:	22/07/2016 (Man. Year: 2016)	Chassis No:	WBA8E36080NT89466
Colour:	Blue	Odometer:	89727 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,732.80	1,468.45	2,264.35	60.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,399.80	3,640.45	2,759.35	43.12
+ GST 7.00/7.00% (S\$)	447.99	254.83	193.16	43.12

Nett Amount (S\$)	6,847.79	3,895.28	2,952.51	43.12
		<hr/>		
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
		<hr/>		
Nett Liability (S\$)		4,022.73		
		<hr/>		

INSPECTION

Date of Assignment: 26/08/2021

Date Inspected: 27/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts:	143	BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD7192T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*REAR BUMPER CENTRE GUIDE	Serviceable	153.50 FS	*- FS
3	1		*REAR BUMPER CARRIER (ECE)	Serviceable	470.25 FS	*- FS
4	1		*REAR BUMPER TOWING EYE COVER PRIMED	Serviceable	43.70 FS	*- FS
5	1		*REAR BUMPER BLACK TRIM STRIP	Scratched	83.00 FS	*83.00 FS
6	1		*REAR BUMPER PANEL PRIMED (LINES)	Deformed	1,184.75 FS	*1,184.75 FS
7	1		*(S/L) LH PROTECTION FOIL	Serviceable	10.75 FS	*- FS
8	1		*(S/L) RH PROTECTION FOIL	Serviceable	10.75 FS	*- FS
9	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	67.65 FS	*67.65 FS
10	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.60 FS	*- FS
11	4		*BUMPER PDC SENSOR (A89 IMPERIABLAU)	Serviceable	1,484.80 FS	*- FS
12	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)
3,732.80
1,468.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (S\$)			2,667.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >