

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009013/APA3Q2**Date:** 17/04/2023**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210062028   |
| <b>Claimant Vehicle No :</b> | EY5499X                              | <b>Insured Vehicle No :</b> | GBF1448E     |
| Date of Loss:                | 21/08/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3911247692SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>EY5499X</b>                    | Engine No:  | 2AZC477873   |
| Make & Model:               | TOYOTA ESTIMA, 2.4 AERAS (A)      | Chassis No: | ACR507071132 |
| Reg. Date:                  | 12/02/2009 (Man. Year: 2008)      | Odometer:   | 204887 km    |
| Colour:                     | Grey                              |             |              |
| Engine Capacity:            | 2362 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 215/55 R17       | Rear Tyre Size:  | 215/55 R17       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 11,021.19         | 4,012.66          | 7,008.53          | 63.59         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,370.00          | 1,690.00          | 1,680.00          | 49.85         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>14,391.19</b>  | <b>5,702.66</b>   | <b>8,688.53</b>   | <b>60.37</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>4,500.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 14,391.19         | 4,500.00          | 9,891.19          | 68.73         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,007.38          | 315.00            | 692.38            | 68.73         |
| <b>Nett Amount (S\$)</b>                        | <b>15,398.57</b>  | <b>4,815.00</b>   | <b>10,583.57</b>  | <b>68.73</b>  |
| <b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b> |                   | 560.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>5,375.00</b>   |                   |               |

**INSPECTION**

|                             |                          |                                                     |
|-----------------------------|--------------------------|-----------------------------------------------------|
| Date of Assignment:         | 24/08/2021               | Lee Sheng Auto Pte Ltd (HQ)                         |
| Date Inspected:             | 24/08/2021 Inspected At: | 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit |
| Estimated Period of Repair: | 6.0 days                 | Singapore 417883                                    |

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's | Amount       |
|-----|-----|----------|-------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *BOOTLID                      | Distorted     | 1,939.50 F | *1,406.00 FL |
| 2   | 1   |          | *BOOTLID HANDLE               | Cracked       | 271.75 F   | *271.75 FL   |
| 3   | 1   |          | *BOOTLID REFLECTOR LH         | Cracked       | 371.50 F   | *281.00 FL   |
| 4   | 1   |          | *BOOTLID REFLECTOR RH         | Cracked       | 371.50 F   | *281.00 FL   |
| 5   | 1   |          | *BOOTLID REFLECTOR CENTRE     | Missing       | 271.48 F   | *271.48 FL   |
| 6   | 1   |          | *REAR END PANEL               | Dented        | 755.40 F   | *755.40 FL   |
| 7   | 1   |          | *REAR END PANEL TOP GARNISH   | Deformed      | 371.90 F   | *246.00 FL   |
| 8   | 10  |          | *REAR END PANEL GARNISH CLIPS | Necessary     | 35.00 F    | *10.00 FL    |
| 9   | 1   |          | *REAR BUMPER                  | Deformed      | 571.75 F   | *571.75 FL   |
| 10  | 1   |          | *REAR BUMPER REFLECTOR LH     | Not Necessary | 121.10 F   | *- FL        |
| 11  | 1   |          | *REAR BUMPER REFLECTOR RH     | Not Necessary | 121.10 F   | *- FL        |
| 12  | 1   |          | *REVERSE SENSOR               | Damaged       | 250.00 F   | *250.00 FL   |
| 13  | 1   |          | *BOOTLID LOCK                 | Damaged       | 450.00 F   | *355.00 FL   |
| 14  | 1   |          | *REAR BUMPER RETAINER         | Not Necessary | 171.48 F   | *- FL        |
| 15  | 1   |          | *REAR BUMPER RETAINER RH      | Not Necessary | 171.48 F   | *- FL        |
| 16  | 1   |          | *BOOTLID INNER DOOR BOARD     | Cracked       | 731.10 F   | *458.00 FL   |
| 17  | 1   |          | *TOYOTA EMBLEM                | Necessary     | 61.50 F    | *61.50 FL    |
| 18  | 1   |          | *TOWING COVER                 | Not Necessary | 61.50 F    | *- FL        |
| 19  | 1   |          | *SPARE TYRE PANEL             | Repair        | 731.35 F   | *- FL        |
| 20  | 1   |          | *SPARE TYRE BOARD             | Not Necessary | 971.75 F   | *- FL        |
| 21  | 1   |          | *ESTIMA EMBLEM                | Necessary     | 98.00 F    | *98.00 FL    |
| 22  | 1   |          | *BOOTLID HINGE LH             | Not Necessary | 191.10 F   | *- FL        |
| 23  | 1   |          | *BOOTLID HINGE RH             | Not Necessary | 191.10 F   | *- FL        |
| 24  | 1   |          | *BOOTLID ABSORBER RH          | Not Necessary | 371.20 F   | *- FL        |
| 25  | 1   |          | *BOOTLID ABSORBER LH          | Not Necessary | 371.20 F   | *- FL        |
| 26  | 1   |          | *WIPER MOTOR                  | Not Necessary | 971.45 F   | *- FL        |
| 27  | 1   |          | *NO PLATE (METAL)             | Bent          | 25.00 FS   | *25.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                 |
|---------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>11,021.19</b> | <b>5,341.88</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$)</b> | 0.00             | 1,329.22        |
| <b>Total Parts (\$)</b>                                 | <b>11,021.19</b> | <b>4,012.66</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                                                                       | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                   |          |                 |                 |
| 1                               | TO KNOCKING ,JACKING WELDING ETC                                                  | New      | 1,600.00        | 800.00          |
| 2                               | SPRAY PAINTING ON BOOTLID ,BUMPER,REAR END PANEL SPARE TYRE PANEL ,FENDER RH & LH | New      | 1,600.00        | 800.00          |
| 3                               | WIRING                                                                            | New      | 50.00           | 30.00           |
| 4                               | APPLY ANTI RUSH                                                                   | New      | 120.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                   |          | <b>3,370.00</b> | <b>1,690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >