



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 9199L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRONT	BROKEN	473.00	430.00
1	FRONT BUMPER LOWER	CRACKED	79.20	38.00
1	FRONT BUMPER LOWER	CRACKED	88.00	38.00
1	FRONT BUMPER REINF (NPA)	NOT NECESSARY	-	-
1	LEFT RETAINER	NOT NECESSARY	19.80	-
1	RIGHT RETAINER	NOT NECESSARY	19.80	-
1	HEADLAMP HOUSING B	NOT NECESSARY	43.56	-
1	HEADLAMP HOUSING B	NOT NECESSARY	43.56	-
1	FRONT BUMPER REINF	NOT NECESSARY	237.60	-
1	FRONT GRILLE	BROKEN	303.60	230.00
1	FRONT GRILLE CHROM	BROKEN	257.00	195.00
	COST PLUS 10%		-	93.10
			1,565.12	1,024.10
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRY ITEMS (SN)	NECESSARY	100.00	20.00
1	LEFT SIDE HEAD LAM (SN) (\$480.00) (50%)	CRACKED	539.00	240.00
1	RIGHT SIDE HEAD LA (SN) (\$480.00) (50%)	CRACKED	539.00	240.00
			1,178.00	500.00
	<u>LABOUR</u>			
	REMOVING AND REPLAICNG ALL ACCIDENT DAMAGE PARTS.		1,350.00	400.00
	SPRAY PAINTING FRONT BUMPER PANEL AND FRONT HOOD.		900.00	400.00
	CLEAR FAULT AFTER REPAIR AND CODE THE HEADLIGHT.		100.00	30.00
			2,350.00	830.00
	GRAND TOTAL		5,093.12	2,354.10

Report Ref No. CS/AWA21009014/Evf3e2



RECOMMENDED COST OF REPAIRS			2,354.10
-----------------------------	--	--	----------

Report Ref No. CS/AWA21009014/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.