



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 2387K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COMPANY DOOR STICKER (SN) (NPA)	NOT NECESSARY	-	-
1	R/F DOOR ASSY (SN)	DENTED	1,419.40	1,419.40
1	PROTECTOR, FR DOOR P (SN)	NOT NECESSARY	65.00	-
1	SEAL, FR FENDER TO C (SN)	NOT NECESSARY	33.30	-
1	R/F DOOR STEP (SN)	BROKEN	400.40	400.40
1	APRON, FENDER SIDE (SN)	CUT	144.10	144.10
1	PLATE, FR DOOR NAME (SN)	NECESSARY	58.00	58.00
1	PLATE, FR DOOR NAME (SN)	NECESSARY	35.30	35.30
1	HEADLAMP ASSY, RH (SN)	NOT NECESSARY	1,086.50	-
1	LAMP ASSY, SIDE TURN (SN)	CUT	96.20	96.20
1	WHEEL SUB-ASSY, DISC (SN)	NOT NECESSARY	356.70	-
5	NUT, DOUBLE WHEEL ST (SN)	NOT NECESSARY	120.00	-
1	CAP, FR HUB GREASE (SN)	DENTED	21.80	21.80
1	HUB & DISC ASSY, FR (SN)	NOT NECESSARY	1,086.50	-
1	BEARING, TAPERED ROL (SN)	NOT NECESSARY	105.00	-
1	BEARING, TAPERED ROL (SN)	NOT NECESSARY	154.00	-
1	DISC, FR (SN)	NOT NECESSARY	358.70	-
1	GEAR ASSY, POWER STEERING (SN)	NOT NECESSARY	4,441.10	-
1	ARM, PITMAN (SN)	NOT NECESSARY	275.00	-
1	LINK ASSY, STEERING (SN)	NOT NECESSARY	323.50	-
1	ROD ASSY, TIE (SN)	NOT NECESSARY	530.00	-
1	ARM, STEERING KNUCKL (SN)	NOT NECESSARY	448.80	-
1	KNUCKLE SUB-ASSY, ST (SN)	NOT NECESSARY	604.90	-
1	I-BEAM, FR AXLE (SN)	NOT NECESSARY	1,589.40	-
1	FRT SHOCK ABSORBER ASSY (SN)	NOT NECESSARY	96.00	-
1	BRACKET, FR SHOCK AB (SN)	NOT NECESSARY	70.00	-
1	SPRING ASSY, FR (SN)	NOT NECESSARY	1,180.10	-
			15,199.70	2,225.20

Report Ref No. CS/UOI21009016/Eqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SUPPLY JOINT PANEL SEALANT.		200.00	100.00
	CHECK WIRING AND CONDUCT WATER TEST.		220.00	220.00
	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR.		880.00	440.00
	TO CONDUCT FULL WHEEL ALIGNMENT.		440.00	440.00
	REPLACE RIM AND WHEEL BALANCING.	NOT NECESSARY	149.60	-
	TO RESET ECU AND REPROGRAMME.		220.00	220.00
	REPLACE RH FRONT SUSPENSION.	NOT NECESSARY	1,760.00	-
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS.		2,640.00	880.00
	RESPRAY ACC AFFECTED AREAS.		1,980.00	1,980.00
			8,489.60	4,280.00
	GRAND TOTAL		23,689.30	6,505.20

RECOMMENDED COST OF REPAIRS			6,505.20
LESS EXCESS			-800.00
NETT LIABILITY			5,705.20

Report Ref No. CS/UOI21009016/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.