

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21009018/KVF3N2**Date:** 06/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210051177
Claimant Vehicle No :	GBK1969S	Insured Vehicle No :	GBL3099J
Date of Loss:	26/08/2021	Nature of Claim:	TP
		Claim No:	0633563987SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK1969S	Engine No:	HR16159790D
Make & Model:	NISSAN NV200, 1.6 PETROL (A)	Chassis No:	JN1YAAM20Z0000531
Reg. Date:	31/01/2020 (Man. Year: 2019)	Odometer:	72551 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Windforce 9 mm	Rear Left Side:	Windforce 9 mm
Front Right Side:	Windforce 9 mm	Rear Right Side:	Windforce 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,121.84	15,852.63	12,269.21	43.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,630.00	4,840.00	2,790.00	36.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,751.84	20,692.63	15,059.21	42.12
Approved Total (Overridden) (S\$)		16,500.00		
Nett Amount (S\$)	35,751.84	16,500.00	19,251.84	53.85

INSPECTION

Date of Assignment:	27/08/2021		160 SIN MING DRIVE #03-18/19
Date Inspected:	27/08/2021	Inspected At:	SIN MING AUTOCITY
			SINGAPORE 575722
			REPAIRER: EM SOLUTION PTE LTD
Estimated Period of Repair:	12.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,978.40 FL	*1,835.00 FL
2	1		*TAILGATE LOGO	Necessary	79.90 FL	*59.70 FL
3	1		*TAILGATE EMBLEM NV200	Necessary	145.20 FL	*87.00 FL
4	1		*TAILGATE EMBLEM VANETTE	Necessary	68.60 FL	*68.60 FL
5	1		*TAILGATE OUTER GARNISH	Buckled	351.50 FL	*351.50 FL
6	2		*TAILGATE LICENCE LAMPS	Serviceable	83.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Dented/Jammed	202.60 FL	*202.60 FL
8	1		*TAILGATE INNER LOCK ACTUATOR	Serviceable	281.30 FL	*- FL
9	1		*TAILGATE INNER PULL POCKET	Serviceable	89.60 FL	*- FL
10	1		*TAILGATE INNER TRIM	Cracked	286.90 FL	*180.50 FL
11	15		*TAILGATE INNER TRIM CLIPS	Necessary	67.50 FL	*67.50 FL
12	1		*TAILGATE LOCK STRIKER	Distorted	55.60 FL	*55.60 FL
13	1		*TAILGATE W/STRIP	Dented/Cut	241.20 FL	*241.20 FL
14	2		*TAILGATE HINGES-L/R	Repair	137.00 FL	*- FL
15	2		*TAILGATE DAMPERS-L/R	Serviceable	379.20 FL	*- FL
16	2		*TAILGATE SIDE STOPPERS-L/R	Serviceable	97.20 FL	*- FL
17	2		*TAILGATE SIDE STOPPER STICKERS-L/R	Not Necessary	110.20 FL	*- FL
18	1		*TAILGATE WIPER MOTOR	Serviceable	431.20 FL	*- FL
19	2		*TAILLAMPS-L/R	N/s Cracked/O/s Cut	566.40 FL	*517.40 FL
20	1		*TAILLAMP FILLER PANELS-L/R	N/s Bent	850.00 FL	*425.00 FL
21	1		*REAR BUMPER	Bent	632.70 FL	*481.10 FL
22	1		*REAR BUMPER TOW COVER	Serviceable	18.60 FL	*- FL
23	2		*REAR BUMPER REFLECTORS-L/R	Serviceable	123.00 FL	*- FL
24	1		*REAR BUMPER INNER FOAM	Cracked	194.70 FL	*118.00 FL
25	1		*REAR BUMPER SIDE RETAINERS L/R	N/s Cracked	85.80 FL	*42.90 FL
26	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
27	1		*REAR END PANEL-OUTER	Bent	411.50 FL	*162.40 FL
28	1		*REAR END PANEL-INNER	Bent	841.80 FL	*644.00 FL
29	1		*REAR END PANEL GARNISH	Dented	128.60 FL	*83.50 FL
30	10		*REAR END PANEL GARNISH CLIPS	Necessary	45.00 FL	*45.00 FL
31	1		*REAR EXHAUST SILENCER	Repair	551.70 FL	*- FL
32	2		*REAR EXHAUST MOUNTINGS	Serviceable	57.20 FL	*- FL
33	1		*REAR FLOOR PANEL	Bent/Buckled	1,556.90 FL	*1,228.40 FL
34	1		*REAR FENDERS-L/R	N/s Buckled	3,583.20 FL	*1,791.60 FL
35	1		*REAR FENDER RAIL GUIDE-LH	Serviceable	176.30 FL	*- FL
36	1		*REAR FENDER AIR VENT-LH	Distorted	86.90 FL	*86.90 FL
37	1		*REAR FENDER INNER TRIM-LH	Serviceable	261.20 FL	*- FL
38	15		*REAR FENDER INNER TRIM CLIPS	Not Necessary	67.50 FL	*- FL
39	1		*REAR FENDER INNER PANEL-LH	Repair	441.70 FL	*- FL
40	1		*REAR FENDER WHEEL HOUSING-LH	Repair	586.90 FL	*- FL
41	1		*REAR SPARE WHEEL CARRIER	Distorted	311.20 FL	*311.20 FL
42	1		*REAR SPARE WHEEL LOCK CATCH	Repair	110.50 FL	*- FL
43	1		*FRONT BONNET	Bent	1,054.30 FL	*881.60 FL
44	1		*FRONT BONNET LOCK	Distorted	121.50 FL	*121.50 FL
45	1		*FRONT BONNET LOCK CABLE	Serviceable	89.90 FL	*- FL
46	1		*FRONT BONNET INSULATOR	Serviceable	110.20 FL	*- FL
47	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
48	1		*FRONT BONNET SEAL	Serviceable	68.20 FL	*- FL
49	2		*FRONT BONNET HINGES-L/R	Repair	91.60 FL	*- FL
50	1		*FRONT BUMPER	Bent	675.40 FL	*502.80 FL
51	1		*FRONT BUMPER TOW COVER	Missing	28.60 FL	*28.60 FL
52	1		*FRONT BUMPER SPONGE	Cracked	280.70 FL	*118.00 FL
53	1		*FRONT BUMPER REINFORCEMENT	Bent	1,014.80 FL	*418.40 FL
54	1		*FRONT BUMPER SIDE RETAINERS-L/R	N/s Distorted	57.20 FL	*28.60 FL
55	2		*FRONT FENDERS-L/R	Repair	1,354.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT GRILLE	Cracked	338.00 FL	*338.00 FL
57	1		*FRONT GRILLE LOGO	Necessary	69.70 FL	*69.70 FL
58	2		*FRONT HEADLAMPS-L/R	Mtg Cracked	1,236.20 FL	*1,236.20 FL
59	2		*FRONT HEADLAMP LOWER GARNISHES-L/R	Mtg Cracked	697.20 FL	*462.00 FL
60	2		*FRONT HEADLAMP PANELS-L/R	Repair	173.00 FL	*- FL
61	1		*FRONT SUPPORT PANEL-TOP	Bent	507.50 FL	*507.50 FL
62	1		*FRONT SUPPORT PANEL GARNISH	Serviceable	126.20 FL	*- FL
63	1		*FRONT SUPPORT PANEL-LOWER	Cracked	295.70 FL	*295.70 FL
64	2		*HORNS	Serviceable	167.60 FL	*- FL
65	1		*AIR CON CONDENSER	Punctured	781.60 FL	*781.60 FL
66	1		*AIR CON DISCHARGE PIPE	Serviceable	411.50 FL	*- FL
67	1		*AIR CON SUCTION PIPE	Serviceable	361.50 FL	*- FL
68	1		*AIR CON LIQUID PIPE	Serviceable	260.90 FL	*- FL
69	1		*AIR CLEANER INTAKE DUCT	Serviceable	69.20 FL	*- FL
70	1		*RADIATOR ASSY	Housing Cracked	762.60 FL	*762.60 FL
71	1		*RADIATOR ELECTRIC FAN ASSY	Cracked	596.30 FL	*596.30 FL
72	1		*RADIATOR SPARE TANK	Serviceable	80.90 FL	*- FL
73	1		*SET FRONT NO PLATE WITH HOLDER	Bent	60.00 FS	*45.00 FS
74	1		*BOT AIR CON OIL	Necessary	65.00 FS	*50.00 FS
75	1		*BOT RADIATOR COOLER	Necessary	65.00 FS	*30.00 FS
76	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
77	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
78	1		*REAR STICKER 6 PAX	Necessary	10.00 FS	*10.00 FS
79	1		*REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
80	1		*SET REAR REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
81	1		*SET REAR NO PLATE WITH HOLDER	Dented	60.00 FS	*45.00 FS
82	1		*REAR FLOOR BOARD	Cracked	450.00 FS	*450.00 FS
83	1		*REAR FLOOR MAT	Torn	280.00 FS	*280.00 FS
84	1		*SET REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
85	1		*REAR TYRE-LH	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,997.60	17,480.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,875.76	1,628.07
Total Parts (\$\$)	28,121.84	15,852.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	180.00	40.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
4	TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS	New	150.00	100.00
5	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
6	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	120.00	60.00
7	TO RESPRAY UNDERCOATING	New	200.00	180.00
8	TO RESPRAY PAINTING AND ETC	New	2,000.00	1,600.00
9	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	4,500.00	2,600.00
Gross Labour Cost (\$\$)			7,630.00	4,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >