

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21009019/EGA3Q2**Date:** 05/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : YM7604Y **Insured Vehicle No :** GBL1997E

Date of Loss: 26/08/2021 Nature of Claim: TP Claim No: MFL2021D0003771

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM7604Y**

Make & Model: NISSAN MKB37BNHRA, 7.7 D (M) Engine No: J08EUC10275

Reg. Date: 30/10/2007 (Man. Year: 2007) Chassis No: MKB37BN00117

Colour: Red Odometer: 459136 km

Engine Capacity: 7684 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Linglong 4 mm Rear Left Side: Linglong 4 mm

Front Right Side: Linglong 4 mm Rear Right Side: Linglong 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,831.19	14,799.26	11,031.93	42.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,200.00	7,050.00	2,150.00	23.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,031.19	21,849.26	13,181.93	37.63
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	35,031.19	7,000.00	28,031.19	80.02
+ GST 7.00/7.00% (S\$)	2,452.18	490.00	1,962.18	80.02
Nett Amount (S\$)	37,483.37	7,490.00	29,993.37	80.02
+ Loss of Use (22.0 x S\$180.00/day) (S\$)		3,960.00		
+ Doc/Search Fee (S\$)		29.00		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		11,579.00		
Global Sum Settlement (S\$)		11,500.00		

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 07/09/2021 Inspected At:

Goldbell Engineering Pte Ltd (Tuas)
10 Tuas Ave 18
Singapore 638894

Estimated Period of Repair: 15.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Oct 2021)	
Parts:	N/A	NISSAN MKB37BNHRA 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM7604Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Broken	1,600.00 FL	*1,600.00 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	685.33 FL	*685.33 FL
3	1		*FRONT CORNER PANEL RH	Dented	1,218.02 FL	*1,218.02 FL
4	1		*FRONT WIPER PANEL	Dented	1,848.61 FL	*1,848.61 FL
5	1		*FRONT STEP GARNISH RH	Dented	312.59 FL	*312.59 FL
6	2		*FRONT STEP RH	Broken	770.44 FL	*770.44 FL
7	1		*FRONT FENDER RH	Dented	743.45 FL	*743.45 FL
8	1		*FRONT BUMPER	Dented	1,916.75 FL	*1,916.75 FL
9	1		*FRONT BUMPER STAY RH	Not Necessary	425.05 FL	*- FL
10	1		*FRONT PANEL CAB	Repair	2,857.70 FL	*- FL
11	1		*FRONT PILLAR RH	Repair	2,630.59 FL	*- FL
12	1		*FRONT DOOR ASSY RH	Dented	2,047.96 FL	*2,047.96 FL
13	1		*FRONT DOOR WINDOW GLASS RUNCHANNEL	Not Necessary	491.82 FL	*- FL
14	1		*FRONT DOOR UPPER HINGE RH	Bent	453.44 FL	*453.44 FL
15	1		*FRONT DOOR LOWER HINGE RH	Bent	453.44 FL	*453.44 FL
16	1		*FRONT DOOR OUTSIDE HANDLE RH	Broken	207.57 FL	*207.57 FL
17	1		*FRONT DOOR REGULATOR ASSY RH	Not Necessary	363.78 FL	*- FL
18	1		*FRONT DOOR INSIDE HANDLE RH	Not Necessary	70.40 FL	*- FL
19	1		*FRONT DOOR LATCH & ACTUATOR RH	Not Necessary	1,200.00 FL	*- FL
20	1		*FRONT DOOR TRIM RH	Not Necessary	1,089.85 FL	*- FL
21	1		*SIDE MIRROR RR VIEW RH	Not Necessary	128.00 FL	*- FL
22	1		*SIDE MIRROR STAY RH	Bent	698.58 FL	*698.58 FL
23	1		*FRONT WHEEL HOUSE COVER RH	Torn	377.90 FL	*377.90 FL
24	1		*FR WHEEL HOUSE SPLASH SHIELD LWR APRON RH	Torn	161.86 FL	*161.86 FL
25	1		*HEADLAMP ASSY RH	Not Necessary	983.85 FL	*- FL
26	1		*FOG LAMP RH	Broken	291.57 FL	*291.57 FL
27	1		*FRONT TURN SIGNAL LAMP RH	Broken	210.78 FL	*210.78 FL
28	1		*FRONT SIDE TURN SIGNAL LAMP RH	Broken	77.42 FL	*77.42 FL
29	1		*BACK OUTER PANEL RH	Dented	1,317.91 FL	*1,317.91 FL
30	1		*IU BRACKET	Necessary	25.00 FS	*25.00 FS
31	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
33	1		*COMPANY STICKER	Necessary	500.00 FS	*300.00 FS
34	1		*UD LOGO	Missing	30.00 FS	*30.00 FS
35	1		*FRONT RIM RH	Bent	250.00 FS	*250.00 FS
36	1		*FRONT TYRE RH (50%)	Torn	180.00 FS	*90.00 FS
37	1		*SIDE STEP UPPER RIM	Necessary	1,200.00 FS	*200.00 FS
38	1		*WOODEN DECK MIDDLE HOLDER RH	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	28,394.66	16,338.62
- List Item Discount on L Items 10.00/10.00% (S\$)	2,563.47	1,539.36
Total Parts (S\$)	25,831.19	14,799.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REPAIR SIDE WOODEN DECK	New	1,300.00	0.00
2	REMOVE AND REPAIR LOWER SIDE STEP RH	New	700.00	400.00
3	RE-ALIGN CABIN HEAD	New	700.00	600.00
4	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN ETC	New	4,000.00	3,600.00
5	TO PUTTY ,CLEAN ,SPRAY AINT AND POLISH ETC	New	2,500.00	2,450.00
Gross Labour Cost (\$\$)			9,200.00	7,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >