

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009024/AVCN2**Date:** 06/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00137242100

Claimant Vehicle No : SMP710X **Insured Vehicle No :** SDY1888U

Date of Loss: 24/08/2021 Nature of Claim: TP Claim No: SNM21D204756/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP710X**

Make & Model: VOLVO XC60, 2.0 T5 (A) Engine No: B4204T110006823

Reg. Date: 21/05/2014 (Man. Year: 2013) Chassis No: YV1DZ40CDE2569807

Colour: Brown Odometer: 143200 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,314.20	9,636.30	12,677.90	56.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,360.00	2,540.00	65.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,214.20	10,996.30	15,217.90	58.05
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	26,214.20	8,800.00	17,414.20	66.43

INSPECTION

Date of Assignment: 05/10/2021

Date Inspected: 27/08/2021 Inspected At: 2020 Spray Painting Pte Ltd (HQ)
53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2021)
Parts:	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP710X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Cracked	2,780.10 F	*2,780.10 FL
2	1		*REAR TAILGATE CHROME GARNISH	Not Necessary	267.30 F	*- FL
3	1		*REAR TAILGATE INNER GARNISH	Not Necessary	868.80 F	*- FL
4	2		*REAR TAILGATE SUSPENSION	Not Necessary	2,314.80 F	*- FL
5	2		*REAR TAILGATE SUSPENSION HINGE	Not Necessary	581.20 F	*- FL
6	1		*REAR TAILGATE LOCK SYSTEM	Damaged	553.70 F	*553.70 FL
7	1		*REAR TAILGATE VOLVO LOGO	Necessary	131.50 F	*131.50 FL
8	1		*REAR TAILGATE XC60 LOGO	Necessary	148.70 F	*148.70 FL
9	1		*REAR TAILGATE T5 LOGO	Necessary	127.80 F	*127.80 FL
10	1		*REAR WIPER ARM	Cut	140.30 F	*140.30 FL
11	1		*REAR WIPER MOTOR	Cracked	356.10 F	*356.10 FL
12	1		*REAR WINDSCREEN	Not Necessary	1,733.60 F	*- FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	290.00 F	*290.00 FL
14	1		*REAR WINDSCREEN HEAT SENSOR	Not Necessary	477.70 F	*- FL
15	1		*REAR SPOILER BRAKE LIGHT	Not Necessary	200.80 F	*- FL
16	1		*REAR LH TAILLIGHT	Cracked	571.30 F	*571.30 FL
17	1		*REAR RH TAILLIGHT	Cracked	571.30 F	*571.30 FL
18	1		*REAR END PANEL	Dented	1,277.40 F	*845.00 FL
19	1		*REAR RE-INFORCEMENT	Repair	1,721.50 F	*- FL
20	1		*REAR BUMPER	Deformed	2,607.80 F	*1,897.00 FL
21	1		*REAR BUMPER STEP PANEL	Deformed	486.30 F	*345.00 FL
22	2		*REAR BUMPER SIDE LH/RH RETAINER	Not Necessary	221.60 F	*- FL
23	1		*REAR BUMPER CENTRE BRACKET	Cracked	96.70 F	*96.70 FL
24	1		*REAR BUMPER LOWER LIP	Deformed	641.70 F	*641.70 FL
25	1		*REAR BUMPER LOWER LDIFFUSER	Deformed	1,321.80 F	*486.00 FL
26	2		*REAR LH/RH BUMPER REFLECTOR	Cracked	244.80 F	*244.80 FL
27	1		*REAR LH EXHAUST CHROME	Not Necessary	363.80 F	*- FL
28	1		*REAR RH EXHAUST CHROME	Not Necessary	363.80 F	*- FL
29	1		*SET REAR REVERSE SENSORS	Damaged	380.00 FS	*380.00 FS
30	8		*REAR BUMPER CLIPS	Necessary	52.00 FS	*52.00 FS
31	1		*REAR NO PLATE CASING	Not Necessary	70.00 FS	*- FS
32	1		*REAR NO PLATE	Not Necessary	70.00 FS	*- FS
33	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,314.20	10,659.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,022.70
Total Parts (\$\$)	22,314.20	9,636.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,RE-FIT,CUT & WELD TO ACCOMMODATE REPAIRS	New	1,800.00	600.00
2	TO SPRAY PAINT PARTS CHANGED AND DAMAGED AREAS	New	1,600.00	700.00
3	WIRING ON REVERSE SENSORS & WINDSCREEN HEAT SENSORS	New	250.00	60.00
4	WATER LEAK TEST	New	250.00	0.00
Gross Labour Cost (\$\$)			3,900.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >