

2020 SPRAY PAINTING PTE LTD.

53 UBI AVENUE 1 #05-15. PAYA UBI INDUSTRIAL PARK.

SINGAPORE 408934. Email: 2020spraypainting@gmail.com

REPAIR ESTIMATE:

VEHICLE No: SMP710X

Chassis No: YV1DZ40CDE2569807

Make/ Model: VOLVO XC60

Date of Accident: 24/08/2021

TP China.
Veron.

Date: 27/08/2021

Invoice No:

YV1DZ40CDE2569807

No.	Parts Description:	Qty	Remarks	Price Amt \$
1	REAR TAILGATE <i>cracked</i>	1		2,780.10
2	REAR TAILGATE CHROME GARNISH <i>new</i>	1		267.30
3	REAR TAILGATE INNER GARNISH <i>new</i>	1		868.80
4	REAR TAILGATE SUSPENSION (\$1,157.40) <i>new</i>	2		2,314.80
5	REAR TAILGATE SUSPENSION HINGE (\$290.60) <i>new</i>	2		581.20
6	REAR TAILGATE LOCK SYSTEM <i>Damaged</i>	1		553.70
7	REAR TAILGATE "VOLVO" LOGO <i>new</i>	1		131.50
8	REAR TAILGATE "XC 60" LOGO <i>new</i>	1		148.70
9	REAR TAILGATE "T5" LOGO <i>new</i>	1		127.80
10	REAR WIPER ARM <i>new</i>	1		140.30
11	REAR WIPER MOTOR <i>cracked</i>	1		356.10
12	REAR WINDSCREEN <i>new</i>	1		1,733.60
13	REAR WINDSCREEN MOULDING <i>new</i>	1		290.00
14	REAR WINDSCREEN HEAT SENSOR <i>new</i>	1		477.70
15	REAR SPOILER BRAKE LIGHT <i>new</i>	1		200.80
16	REAR LH TAILLIGHT <i>cracked</i>	1		571.30
17	REAR RH TAILLIGHT <i>cracked</i>	1		571.30
18	REAR END PANEL <i>Dented</i>	1		1,277.40
19	REAR RE-INFORCEMENT <i>Repair</i>	1		1,721.50
20	REAR BUMPER <i>Deformed</i>	1		2,607.80
21	REAR BUMPER STEP PANEL <i>Deformed</i>	1		486.30
22	REAR BUMPER SIDE LH/ RH RETAINER. \$110.80 <i>cracked</i>	2		221.60
23	REAR BUMPER CENTRE BRACKET <i>cracked</i>	1		96.70
24	REAR BUMPER LOWER LIP <i>Deformed</i>	1		641.70
25	REAR BUMPER LOWER DIFFUSER <i>Deformed</i>	1		1,321.80
26	REAR LH /RH BUMPER REFLECTOR \$122.40 <i>cracked</i>	2		244.80
27	REAR LH EXHAUST CHROME <i>new</i>	1		363.80
28	REAR RH EXHAUST CHROME <i>new</i>	1		363.80
Special Nett Items:				
1	REAR REVERSE SENSORS (1 SET) <i>Damaged</i>	1		380.00
2	REAR BUMPER CLIPS (\$6.50) <i>new</i>	8		52.00
3	REAR NO. PLATE CASING <i>Not new</i>	1		70.00

21,964.20

4	REAR NO. PLATE <i>new</i>	1	70.00
5	REAR WINDSCREEN SOLAR FILM <i>new</i>	1	280.00
	Labour:		
1	TO REMOVE, RE-FIT, CUT & WELD TO ACCOMMODATE REPAIRS.		1,800.00
2	TO SPRAY PAINT PARTS CHANGED AND DAMAGED AREAS.		1,600.00
3	WIRING ON REVERSE SENSORS & WINDSCREEN HEAT SENSORS.		250.00
4	WATER LEAK TEST.		250.00
			4250
			26,214.20



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 10996.34

L/s: 8.8K.

OT Days.

8.8K.

OT Days.