

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009025/EVCN2**Date:** 13/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00088352100
<b>Claimant Vehicle No :</b>	SGX288C	<b>Insured Vehicle No :</b>	SJX1192C
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204744/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGX288C</b>		
Make & Model:	BMW 320I, 1.6 EFFICIENT DYNAMICS (A)	Engine No:	F1673555B48B20A
Reg. Date:	25/06/2020 (Man. Year: 2019)	Chassis No:	WBA5F32000FJ14044
Colour:	Black	Odometer:	21624 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,627.85	4,419.05	1,208.80	21.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,340.00	5,160.00	2,180.00	29.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,967.85</b>	<b>9,579.05</b>	<b>3,388.80</b>	<b>26.13</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	907.75	670.53	237.22	26.13
<b>Nett Amount (\$\$)</b>	<b>13,875.60</b>	<b>10,249.58</b>	<b>3,626.02</b>	<b>26.13</b>

**INSPECTION**

Date of Assignment:	27/08/2021	
Date Inspected:	16/09/2021 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
<b>Parts:</b>	143	BMW 320I 1.6 EFFICIENT DYNAMICS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGX288C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID	Dented	1,322.15 FS	*1,322.15 FS
2	1		*MOUNT,LATERAL	Not Necessary	199.95 FS	*- FS
3	1		*MOUNT,LATERAL	Not Necessary	199.95 FS	*- FS
4	1		*REAR BUMPER CARRIER	Dented	493.80 FS	*493.80 FS
5	1		*ADAPTER	Broken	48.40 FS	*48.40 FS
6	1		*TRIM STRIP (SPORT)	Broken	104.20 FS	*104.20 FS
7	1		*REAR BUMPER LH SIDE GUIDE	Broken	134.30 FS	*134.30 FS
8	1		*REAR BUMPER RH SIDE GUIDE	Broken	134.30 FS	*134.30 FS
9	1		*REAR BUMPER PANEL PRIMED (SP)	Dented	1,281.30 FS	*1,281.30 FS
10	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	48.10 FS	*- FS
11	1		*SET MOUNTING PDC/PMA SENSOR REAR	Not Necessary	69.70 FS	*- FS
12	1		*PLAQUE 74MM	Necessary	71.95 FS	*71.95 FS
13	1		*LETTERING 320I	Necessary	64.75 FS	*64.75 FS
14	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
15	1		*EXPANDING RIVET D=8MM (14 Pcs)	Necessary (6 Pcs only)	15.40 FS	*6.60 FS
16	1		*REAR DIFFUSER	Broken	64.95 FS	*64.95 FS
17	1		*TRUNK LID SEALING	Not Necessary	129.35 FS	*- FS
18	2		*ULTRASONIC SENSOR BLACK	Not Necessary	499.90 FS	*- FS
19	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
20	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
21	1		*REAR LH TRIM PANEL	Broken	75.25 FS	*75.25 FS
22	1		*REAR RH TRIM PANEL	Broken	75.25 FS	*75.25 FS
23	1		*REAR RH LIGHT IN TRUNK LID	Broken	390.25 FS	*390.25 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **5,627.85**      **4,419.05**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER,BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	3,400.00	2,125.00
2	TO RESPRAY REAR BUMPER,BOOT LID AND TAIL PANEL	New	2,666.00	1,826.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
5	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	257.00
7	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,340.00</b>	<b>5,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >