



Your Ref : D20003036MFSH

Date: 26th Oct 2021

Our Ref : CS/FCI21009026/Guf3e2

M/s MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YN 4215B
INSURED VEHICLE: SHA 1458G
ACCIDENT ON 30/07/2020**

Instruction was received to inspect the vehicle Reg. No. YN 4215B. The inspection was conducted on 30/08/2021 at the premises of M/s Boeki Auto & Marine Pte Ltd, 39 Kranji Link, Singapore 728649.

The following vehicle information was recorded:

Registration Number	: YN 4215B
Make/Model	: Isuzu NPR85UH5AKC
Year of Registration	: 2013
Body Colour	: White
Chassis Number	: JAANPR85HD7100349
Engine Capacity	: 2999 cc

The vehicle sustained damages at the front portion. The chassis frame affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 30,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$ 20,847.00)
Nett Liability	<u>S\$ 9,153.00</u>

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.