



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 5200G

| Qty                                | Description of Parts                           | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |                      |                           |                   |
| 1                                  | TAILGATE (CONSISTENT)                          | BENT                 | 1,639.60                  | 1,399.20          |
| 1                                  | TAILGATE EMBLEM "NISSAN" (CONSISTENT)          | NECESSARY            | 211.50                    | 211.50            |
| 1                                  | TAILGATE LOWER MEMBER (CONSISTENT)             | BENT                 | 586.50                    | 586.50            |
| 1                                  | TAILGATE STOPPER - RH (CONSISTENT)             | DENTED               | 48.60                     | 48.60             |
| 1                                  | TAILGATE STOPPER BRACKET - RH (CONSISTENT)     | DISTORTED            | 180.90                    | 180.90            |
| 1                                  | TAILLAMP - RH (CONSISTENT)                     | BROKEN               | 283.50                    | 225.00            |
| 1                                  | TAILLAMP PANEL - RH (CONSISTENT)               | BENT                 | 186.40                    | 168.40            |
| 1                                  | REAR EXHAUST PIPE (CONSISTENT)                 | TO REPAIR SEE LABOUR | 441.60                    | -                 |
| 1                                  | REAR EXHAUST MOUNTING (CONSISTENT)             | SERVICEABLE          | 28.60                     | -                 |
| 1                                  | REAR SIDEGATE LOCK HINGES - RH (CONSISTENT)    | TO REPAIR SEE LABOUR | 195.60                    | -                 |
|                                    | LESS 10% DISCOUNT                              |                      | -380.28                   | -282.01           |
|                                    |  |                      | 3,422.52                  | 2,538.09          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |                      |                           |                   |
| 1                                  | REAR STICKER "70 KM/H" (SN) (CONSISTENT)       | NECESSARY            | 10.00                     | 10.00             |
| 1                                  | REAR STICKER "13 PAX" (SN) (CONSISTENT)        | NECESSARY            | 10.00                     | 10.00             |
| 1                                  | REAR STEP PANEL (SN) (CONSISTENT)              | TO REPAIR SEE LABOUR | 250.00                    | -                 |
| 1                                  | SET REAR REVERSE SENSOR (SN) (CONSISTENT)      | CRACKED              | 280.00                    | 200.00            |
| 1                                  | SET REAR REFLECTIVE MARKINGS (SN) (CONSISTENT) | NECESSARY            | 180.00                    | 60.00             |
| 1                                  | REAR NO. PLATE (SN) (CONSISTENT)               | SERVICEABLE          | 40.00                     | -                 |
|                                    |  |                      | 770.00                    | 280.00            |
| <b><u>LABOUR</u></b>               |  |                      |                           |                   |
|                                    | TO CHECK REAR ELECTRICAL WIRING.               |                      | 50.00                     | 20.00             |
|                                    | TO RESPRAY UNDERCOATING.                       |                      | 60.00                     | 60.00             |
|                                    | TO RESPRAY PAINTING AND ETC.                   |                      | 800.00                    | 540.00            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|-----------|---------------------------|-------------------|
|   | PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE, REAR SIDEGATE LOCK HINGES - RH AND REAR STEP PANEL. |           | 800.00                    | 600.00            |
|   |  |           | 1,710.00                  | 1,220.00          |
| <b>GRAND TOTAL</b>  |  |           | <b>5,902.52</b>           | <b>4,038.09</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |           |                           | <b>3,200.00</b>   |

Report Ref No. CS/ASM21009027/Kvce2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.