

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009029/GTF3N2**Date:** 29/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLG4383P**Insured Vehicle No :** SKX9319R

Date of Loss: 25/08/2021

Nature of Claim: TP

Claim No: 9333566812SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLG4383P**

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZRX575081

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No: MR053REH104551357

Colour: White

Odometer: 103829 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/45ZR17

Rear Tyre Size: 215/45ZR17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment: 27/08/2021

Date Inspected: 30/08/2021 Inspected At:

BLK 4 YEW TEE IND EST 393 - J

WOODLANDS ROAD

SINGAPORE 677969

REPAIRER: ENG SOON PAINTING SVC

Estimated Period of Repair: 9.0 days

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$60,000.00 (EST)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT BUMPER	Dented	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Dented	0.00 F	*- F
8	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
10	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
11	1		*BONNET	Buckled	0.00 F	*- F
12	1		*REAR BUMPER	Dented	0.00 F	*- F
13	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
14	1		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
15	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
16	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
17	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
18	1		*REAR END PANEL	Buckled	0.00 F	*- F
19	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
20	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
21	1		*BOOTLID	Buckled	0.00 F	*- F
22	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
23	1		*BOOTLID LOCK	Bent	0.00 F	*- F
24	1		*BOOTLID RUBBER	Distorted	0.00 F	*- F
25	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
26	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
27	1		*REAR LH FENDER	Repair	0.00 F	*- F
28	1		*ANTENNA	Cracked	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**
**0.00**
**0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >