



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4202Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	848.90	680.00
2	FRONT BUMPER BRACKETS	TO REPAIR SEE LABOUR	126.40	-
1	FRONT BUMPER N/S SIDE GRILLE	NOT NECESSARY	87.30	-
1	N/S HEADLAMP ASSY	BROKEN	1,178.90	1,178.90
1	RADIATOR GRILLE	BROKEN	595.70	595.70
	LESS 25% DISCOUNT		-709.30	-613.65
			2,127.90	1,840.95
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE (SN)	SCRATCHED	50.00	25.00
			50.00	25.00
	<u>LABOUR</u>			
	TO REMOVE LAMPS, NECESSARY WIRINGS.		40.00	20.00
	LABOUR TO REMOVE DAMAGED PARTS, CHECK, REPAIRS, REPLACE AND REFIT SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKETS.		480.00	240.00
	TO SPRAY PAINTING REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE, INCLUDING PUTTY.		580.00	350.00
	TO RUST PROOFING DAMAGED PORTIONS AND REPLACEMENT PARTS.	NOT NECESSARY	80.00	-
			1,180.00	610.00
GRAND TOTAL			3,357.90	2,475.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/SMR21009031/Gny3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.