

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009034/EGS3Q2**Date:** 14/12/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLK9288C	Insured Vehicle No :	SLV9667J
Date of Loss:	26/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9288C	Engine No:	8ARZ047787
Make & Model:	LEXUS IS200, 2.0 (A)	Chassis No:	JTHBA1D2805032851
Reg. Date:	28/11/2016 (Man. Year: 2016)	Odometer:	88271 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,061.10	3,633.40	427.70	10.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,576.50	5,906.50	1,670.00	22.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,637.60	9,539.90	2,097.70	18.03
+ GST 7.00/7.00% (S\$)	814.63	667.79	146.84	18.03
Nett Amount (S\$)	12,452.23	10,207.69	2,244.54	18.03
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,815.14		

INSPECTION

Date of Assignment:	27/08/2021		
Date Inspected:	01/09/2021	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	143	LEXUS IS200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK9288C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*PANEL DOOR FRT RH	Dented	1,361.30 FS	*1,361.30 FS
3	1		*TAPE ,BLACK OUT FR RH	Necessary	69.90 FS	*69.90 FS
4	1		*SEALANT	Necessary	200.00 FS	*200.00 FS
5	1		*TAPE ,BLACK OUT FR	Necessary	38.40 FS	*38.40 FS
6	1		*WEATHERSTRIP ,FR	Necessary	62.30 FS	*62.30 FS
7	1		*MOULDING RR DOOR RH	Necessary	75.40 FS	*75.40 FS
8	1		*R/FRT UPP DOOR HINGE	Not Necessary	98.20 FS	*- FS
9	1		*R/FRT DOOR LOW HINGE	Not Necessary	112.00 FS	*- FS
10	1		*PANEL SUB-ASSY ,RR	Dented	1,138.70 FS	*1,138.70 FS
11	1		*TAPE ,BLACK OUT RR	Necessary	38.40 FS	*38.40 FS
12	1		*TAPE ,BLACK OUT RR	Necessary	65.90 FS	*65.90 FS
13	1		*L/R EAR DOOR PROTECTOR	Necessary	55.60 FS	*55.60 FS
14	1		*MOULDING ,RR DOOR	Necessary	71.40 FS	*71.40 FS
15	14		*RIVET	Necessary	21.00 FS	*21.00 FS
16	1		*HINGE ASSY ,RR DOOR	Not Necessary	99.60 FS	*- FS
17	1		*R/RR LOW DOOR HINGE	Not Necessary	87.90 FS	*- FS
18	1		*PROTECTOR ,QUARTER RH	Necessary	29.00 FS	*29.00 FS
19	1		*PROTECTOR ,ROCKER	Necessary	47.90 FS	*47.90 FS
20	1		*PROTECTOR ,ROCKER	Necessary	26.90 FS	*26.90 FS
21	2		*PROTECTOR ,SIDE	Necessary	42.20 FS	*42.20 FS
22	1		*PROTECTOR ,SIDE	Necessary	21.10 FS	*21.10 FS
23	4		*PROTECTOR ,ROCKER	Necessary	46.40 FS	*46.40 FS
24	11		*CLIP ,ROCKER PANEL	Necessary	121.00 FS	*121.00 FS
25	6		*RETAINER SIDE	Necessary	39.60 FS	*39.60 FS
26	1		*CLIP	Necessary	11.00 FS	*11.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,061.10** **3,633.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER R/F AND R/R DOORS COMPONENT AND MECHANISM TO NEW DOOR SHELLS	New	1,732.00	1,732.00
2	REMOVE/REFIX RHS ROCKER MLDG	New	433.00	433.00
3	REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR CENTRE PILLAR ,RHS ROCKER PANEL AND FIT NEW PARTS	New	2,598.00	1,299.00
4	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,597.00	2,226.00
5	TO RESET ECU & REPROGRAMME	New	216.50	216.50
Gross Labour Cost (\$)			7,576.50	5,906.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >