

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009044/GGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210014925
Claimant Vehicle No :	SHC6829B	Insured Vehicle No :	SMQ1399A
Date of Loss:	26/08/2021	Nature of Claim:	TP
		Claim No:	5719070161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6829B	Engine No:	D4FDEH313582
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5594183
Reg. Date:	03/08/2015 (Man. Year: 2014)	Odometer:	487725 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,319.80	2,446.00	1,873.80	43.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,170.00	1,330.00	53.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,819.80	3,616.00	3,203.80	46.98
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	6,819.80	2,850.00	3,969.80	58.21
+ GST 7.00/7.00% (S\$)	477.39	199.50	277.89	58.21
Nett Amount (S\$)	7,297.19	3,049.50	4,247.69	58.21
+ Car Rental (6.0 x S\$50.99/day) (S\$)		305.94		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,357.44		
Global Sum Settlement (S\$)		3,350.00		

INSPECTION

Date of Assignment:	27/08/2021	
Date Inspected:	27/08/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID CRDI	Necessary	29.00 FL	*29.00 FL
2	1		*BOOT LID RUBBER WEATHERSTRIP	Twisted	96.00 FL	*96.00 FL
3	1		*BOOT LID LOWER GARNISH	Cut	290.00 FL	*290.00 FL
4	1		*O/S TAIL LAMP	Cracked	421.00 FL	*421.00 FL
5	1		*O/S REFLECTOR	Not Necessary	350.00 FL	*- FL
6	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
7	1		*REAR BUMPER LOWER COVER	Distorted	206.00 FL	*206.00 FL
8	1		*REAR BUMPER SIDE BRACKET O/S & N/S	O/S Cut / N/S Not Necessary	58.00 FL	*29.00 FL
9	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	607.00 FL	*607.00 FL
11	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	108.00 FL	*- FL
12	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
13	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
14	1		*REAR BUMPER REFLECTOR O/S	Cracked	46.00 FL	*46.00 FL
15	1		*EXHAUST PIPE	Not Necessary	1,009.00 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
17	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
18	1		*SET BOOTLID LOWER GARNISH CLIPS	Necessary	60.00 FS	*60.00 FS
19	1		*SET BOOTLID STICKERS	Necessary	100.00 FS	*100.00 FS
20	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
21	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS
22	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,730.00	2,688.00
- List Item Discount on L Items 10.00/10.00% (S\$)	410.20	242.00
Total Parts (S\$)	4,319.80	2,446.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	40.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/WELD ,CUT -OFF THE END PANEL INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR O/S FENDER ETC	New	950.00	360.00
5	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL ,REAR O/S FENDER	New	1,000.00	720.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	0.00
Gross Labour Cost (S\$)			2,500.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >