



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107447

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 28/10/2021
Reference CC4/FCI21009045/Kra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GV 2541T
Insured Veh. XE 2634Y
Claim No. D21002422MFVS/2
Policy No. D-21097029MFVS
Accident Date 26/08/2021
Inspection Date 27/08/2021

Description	Total
Survey Inspection	270.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	270.00
GST (7%)	18.90
Grand Total	288.90

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21009045/Kra3q2	
			Date: 28/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 2634Y	Veh. Inspected	GV 2541T
	Policy No.	D-21097029MFVS	Coverage (\$)	0.00
	Claim No.	D21002422MFVS/2	Excess (\$)	0.00
	Assign From	CHRIS LIM	Assign Date	27/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JTFAT35Y503000416	Colour	SILVER
	Odometer	634732 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15X8	YOKOHAMA	6 mm
	R/H Rear Tyre	155 R12X8 (D)	FALKEN	3/3 mm
	L/H Rear Tyre	155 R12X8 (D)	FALKEN	3/3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/08/2021	Inspection Date	27/08/2021
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 2541T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILLAMP LH	CRACKED	193.80	193.80
1	REAR TAILGATE	BENT	1,139.20	1,139.20
1	SIDE GATE LH	BENT	1,381.25	1,381.25
	LESS 25% DISCOUNT		-678.56	-678.56
			2,035.69	2,035.69
	<u>SPECIAL NETT ITEMS</u>			
1	'70KM/H' STICKER (SN)	NECESSARY	10.00	10.00
1	'13 PAX' STICKER (SN)	NECESSARY	10.00	10.00
1	TAILGATE INNER PROTECTOR (SN)	SERVICEABLE	320.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	SET REVERSE CAMERA (SN)	SERVICEABLE	380.00	-
			920.00	20.00
	<u>LABOUR</u>			
	REMOVE AND REFIT TAILLAMPS ,TAILGATE,SIDE GATE .TO KNOCK AND REPAIR REAR END PANEL ,REAR FLOOR BOARD PANEL ,CABIN REAR PANEL AND REALIGN THE SAME.		600.00	540.00
	REMOVE AND REFIT REAR TRUCK ASSY ,REPAIR AND REALIGN REAR TRUCK CROSS MEMBER ,MOUNTING INCLUDING REMOVE,REFIT INNER PROTECTOR & REALIGN CABIN AND TRUCK POSITION.		800.00	600.00
	PUTTY AND RESPRAY ON CABIN REAR PANEL,REAR PILLAR ,REAR TRUCK TAILGATE ,SIDE GATES ,REAR END PANEL & FRT GATE.		1,000.00	900.00
			2,400.00	2,040.00
GRAND TOTAL			5,355.69	4,095.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CC4/FCI21009045/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 2541T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 2541T

RE-INSPECTION

