

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 7027X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	695.00	627.00
1	N/S FRONT BUMPER SIDE RETAINER	NOT NECESSARY	23.00	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	428.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	159.00	-
4	FRONT BUMPER PARKING SENSOR @\$147.00	NOT FITTED	588.00	-
4	FRONT BUMPER PARKING SENSOR HOLDER @\$23.00	NOT FITTED	92.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	389.00	-
1	FRONT BUMPER FOAM	NOT NECESSARY	68.00	-
1	N/S HEADLAMP	CRACKED	1,558.00	1,558.00
1	N/S HEADLAMP BRACKET	CRACKED	23.00	23.00
1	N/S FRONT BUMPER FOG LAMP	CRACKED	186.00	186.00
1	N/S FRONT BUMPER FOG LAMP TRIM	DEFORMED	118.00	118.00
1	N/S FRONT FENDER	TO REPAIR SEE LABOUR	385.00	-
1	FRONT SUPPORT PANEL (ADDITIONAL)	CRACKED	567.00	567.00
1	LEFT FRONT FENDER INNER SHIELD (ADDITIONAL)	TORN	67.50	67.50
1	SET FRONT BUMPER CLIPS (ADDITIONAL)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-538.65	-318.65
			4,847.85	2,867.85
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	NOT NECESSARY	60.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF N/S FRONT FENDER.		650.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		650.00	400.00
			1,520.00	1,020.00
	GRAND TOTAL		6,367.85	3,887.85

Report Ref No. CS/AGI21009047/Uqf3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			3,887.85	
-----------------------------	--	--	----------	--

Report Ref No. CS/AGI21009047/Uqf3n2

CHUA KANG SENG

Licensed Appraiser