

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009048/APA3Q2**Date:** 24/03/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMS3925H **Insured Vehicle No :** SMH2011J

Date of Loss: 24/08/2021 Nature of Claim: TP Claim No: 5677197641SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS3925H**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZR574217

Reg. Date: 07/02/2017 (Man. Year: 2016) Chassis No: MR053REH104551098

Colour: Silver Odometer: 173520 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,301.35	5,800.12	6,501.23	52.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	1,170.00	2,650.00	69.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,121.35	6,970.12	9,151.23	56.76
Approved Total (Overridden) (\$\$)		5,550.00		
Nett Amount (\$\$)	16,121.35	5,550.00	10,571.35	65.57
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 26/08/2021

Date Inspected: 26/08/2021 Inspected At: T & C Automotive (HQ)
1 KAKI BUKIT AVE 6., #01-49, AUTOBAY
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	531.50 FL	*531.50 FL
2	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
3	2		*FRONT BUMPER RH/LH SIDE RETAINER	Not Necessary	363.80 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	374.45 FL	*374.45 FL
5	1		*FRONT BUMPER FOAM	Cracked	189.90 FL	*189.90 FL
6	1		*FRONT GRILLE BASE	Cracked	353.10 FL	*353.10 FL
7	1		*FRONT GRILLE CHROME (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*FRONT GRILLE TOYOTA LOGO	Necessary	121.35 FL	*121.35 FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	148.10 FL	*- FL
10	2		*FOG LAMP GARNISH RH/LH	Not Necessary	371.10 FL	*- FL
11	2		*FOG LAMP RH/LH	Not Necessary	742.90 FL	*- FL
12	2		*HEADLAMP LH/RH	Cracked	5,998.20 FL	*5,998.20 FL
13	2		*HEADLAMP CHROME LH/RH	Not Necessary	288.50 FL	*- FL
14	2		*HEADLAMP LH/RH LOWER BRACKET	Not Necessary	342.90 FL	*- FL
15	1		*BONNET	Not Necessary	1,248.10 FL	*- FL
16	1		*BONNET RUBBER	Not Necessary	122.10 FL	*- FL
17	1		*BONNET CHROME (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*BONNET LOCK	Damaged	135.00 FL	*135.00 FL
19	1		*SUPPORT PANEL ASSY	Repair	1,074.10 FL	*- FL
20	1		*SUPPORT STAY PANEL	Not Necessary	115.70 FL	*- FL
21	1		*SUPPORT PANEL GARNISH	Not Necessary	73.00 FL	*- FL
22	8		*SUPPORT GARNISH CLIP	Not Necessary	40.00 FL	*- FL
23	1		*RADIATOR	Not Necessary	2,148.90 FL	*- FL
24	1		*AIR-CON CONDENSER	Not Necessary	1,289.10 FL	*- FL
25	2		*FRONT CHASSIS RH/LH (NPA)	Repair	0.00 FL	*- FL
26	1		*FRONT NUMBER PLATE W/CASING	Not Necessary	150.00 FS	*- FS
27	1		*COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,331.80	7,733.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,030.45	1,933.38
Total Parts (\$\$)	12,301.35	5,800.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REWIRING REFOCUS HEADLAMP	New	120.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	500.00
3	PUTTY AND SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,200.00	600.00
4	TO KNOCKED AND STRAIGHTEN FRONT CHASSIS	New	1,200.00	0.00
5	REMOVE AND REPLACE RADIATOR ,AIR-CON CONDENSER AND CHARGE UP GAS	New	380.00	0.00
6	ANTI-RUST UNDERCOAT	New	120.00	40.00
Gross Labour Cost (S\$)			3,820.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >