LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must Bake Jukaki Bukie Avenue 6, Autobay #01-49, Singapore 417883 is subject to final approval from Insurance Company

ESTIMATE

T & C AUTOMOTIVE

Contact: 9007 5148, Chai

Date: 25/08/2021 Acknowledged by Repairer Mehicle No.: SMS3925H

Chassis: MR053REH104551098

TP Alb. Xiao Tong

_		VIOO 10 X			
	Descriptions	Quantity	Unit Price	Total Amount	
	Spare Parts Front bumper Delac		4504.50	4=04=04	
		1	\$531.50	\$531.50	
	Front bumper clip Nu	10	\$5.00	\$50.00 %	
	Front bumper rh/lh side retainer Not New	2	\$181.90	\$363.80	
	Front bumper reinforcement	1	\$374.45	\$374.45	
	Front bumper foam leacled	1	\$189.90	\$189.90	
	Front grille base crucked	1	\$353.10	\$353.10	
	Front grille chrome NR NR	1		\$0.00 \(\times \)	
	Front grille "Toyota" logo NCC	1	\$121.35	\$121.35	
	Front bumper lower grille Not New	1	\$148.10	\$148.10	
	Fog lamp garnish rh/lh	1	\$371.10	\$371.10 \(\)	
	Fog lamp rh/lh Headlamp rh/lh Cracked	2 2 2	\$371.45	\$742.90 🗸	
	Headlamp rh/lh	2	\$2,999.10	\$5,998.20	
	Headlamp chrome rh/lh } Hee Nec		\$144.25	\$288.50 X	
	Headlamp rh/Lh lower bracket	2	\$171.45	\$342.90 %	
	Bonnet 2	1	\$1,248.10	\$1,248.10	
	Bonnet rubber Ne Nec	1	\$122.10	\$122.10	
	Bonnet chrome	1		\$0.00	
	Bonnet lock Danage	1	\$135.00	\$135.00	
	Support panel assy Reco	1	\$1,074.10	\$1,074.10	
	Support stay panel ?	1	\$115.70	\$115.70 *	
	Support panel garnish	1	\$73.00	\$73.00 4	
	Support garnish clip	7722.(0 8	\$5.00	\$40.00	
	Radiator	1 1 20 3	\$2,148.90	\$2,148.90	
	Air-con condenser	$(0, \infty, 0, 1)$ 1	\$1,289.10	\$1,289.10	
	Front chassis rh/lh Rejul	580012	repair	repair	
	Troncendosis m, m			\$16,121.80	A HARD SHAP
			Less 25%	\$4,030.45	
			2033 2370	\$12,091.35	
	Constal Nett			712,051.55	
	Special Nett	1	¢150.00	\$150.00 ⊀	
	Front number plate w/casing	1	\$150.00	A CONTRACTOR OF THE CONTRACTOR	
	Coolant	1	\$60.00	\$60.00 *	
			Sub-Total 3	\$210.00	
	Labour				
	Rewiring refocus headlamp.			\$120.00 30	
	Panel beating charges to remove and replace,	to cut and weld, to knock a	and reshape	-5	
	damaged parts & areas.			\$800.00	
	8-1-1				
	Putty and spray painting all affected parts & ar	eas.		\$1,200.00	
	To knocked and straighten front chassis.			\$1,200.00 *	IDO
	Remove and replace radiator, air-con condense	er and charge up gas		\$380.00	110
	Anti-rust undercoat.			\$120.00 40	
	Allti-rust undercoat.		Total Labour	\$3,820.00	
		Total	l Repair Cost	\$16,121.35	
				0 000 / 0	

total: 690:121 1/5: 5550: 04 Days