

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21009049/RGA3Q2**Date:** 04/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHB432G**Insured Vehicle No :** SMU5016H

Date of Loss: 21/08/2021

Nature of Claim: TP

Claim No: 0661256025SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB432G**

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR6115337

Reg. Date: 03/09/2014 (Man. Year: 2014)

Chassis No: JTDKN36U205747981

Colour: Maroon

Odometer: 746251 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 6 mm

Rear Left Side: Sailun 6 mm

Front Right Side: Sailun 6 mm

Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,562.91	0.00	4,562.91	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,674.00	480.00	1,194.00	71.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,236.91	480.00	5,756.91	92.30
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$66.00/day) (S\$)		198.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		835.00		
Global Sum Settlement (S\$)		800.00		

INSPECTION

Date of Assignment: 25/08/2021

Date Inspected: 25/08/2021 Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F
2	1		*HEAD LAMP LH	Not Necessary	945.20 F	*- F
3	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
4	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
5	1		*GRILLE RADIATOR	Not Necessary	310.60 F	*- F
6	1		*LENS & BODY ,FR TURN LH	Not Necessary	511.80 F	*- F
7	1		*BRACKET ,FR TURN UPPER LH	Not Necessary	24.40 F	*- F
8	1		*BRACKET ,FR TURN LOWER LH	Not Necessary	26.00 F	*- F
9	1		*BRACKET ,FR TURN CENTER LH	Not Necessary	58.20 F	*- F
10	1		*FOG LAMP LH	Not Necessary	280.10 F	*- F
11	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
12	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
13	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
14	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
15	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
16	1		*BUMPER CLIP	Not Necessary	1.61 F	*- F
17	1		*BUMPER GRILLE SUB-ASSY LOWER	Repair	311.10 F	*- F
18	1		*COVER ,FR BUMPER HOLE LH	Repair	18.50 F	*- F
19	1		*BUMPER FRT	Repair	482.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					4,562.91	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	558.00	280.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,674.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >