

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009050/AEA3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SGQ818K **Insured Vehicle No :** SMX2979H

Date of Loss: 22/08/2021 Nature of Claim: TP Claim No: 6956064478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGQ818K**

Make & Model: TOYOTA ESTIMA AERAS, 2.4 G-EDITION (A) Engine No: 2AZF371478

Reg. Date: 31/07/2010 (Man. Year: 2010) Chassis No: ACR500112821

Colour: Brown Odometer: 145310 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,068.75	1,272.50	796.25	38.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	800.00	600.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,468.75	2,072.50	1,396.25	40.25
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,468.75	1,600.00	1,868.75	53.87
+ GST 7.00/7.00% (S\$)	242.81	112.00	130.81	53.87
Nett Amount (S\$)	3,711.56	1,712.00	1,999.56	53.87
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		2,212.00		

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 24/08/2021 Inspected At: J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOGO EMBLEM	Necessary	75.00 FL	*75.00 FL
2	1		*LIMITED EDITION EMBLEM	Necessary	75.00 FL	*75.00 FL
3	1		*REAR BUMPER	Deformed	785.00 FL	*785.00 FL
4	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	25.00 FL	*- FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	120.00 FL	*- FL
6	2		*REAR BUMPER RETAINER LONG	Not Necessary	120.00 FL	*- FL
7	2		*REAR BUMPER RETAINER SHORT	Necessary	110.00 FL	*110.00 FL
8	1		*REAR BUMPER SPONGE	Not Necessary	70.00 FL	*- FL
9	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	1		*END PANEL	Not Necessary	660.00 FL	*- FL
11	1		*BOOTLID RUBBER	Cut	355.00 FL	*355.00 FL
12	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	2,675.00	1,630.00
- List Item Discount on L Items 25.00/25.00% (\$\$)		606.25	357.50
	Total Parts (\$\$)	2,068.75	1,272.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			1,400.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >