LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009055/VQF3E2

10/09/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle FBQ5306Y Insured Vehicle No:

SCY88E No:

Date of Loss: 25/08/2021 Nature of Claim: TP 1232538715SG Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ5306Y**

Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS G3J8E0101884 Engine No:

Reg. Date: 23/10/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ054600

Odometer: Colour: Red 0 km

Engine Capacity: 155 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 140/70-14

Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/08/2021

Ong Motor Trading (MACPHERSON RD) Date Inspected: 30/08/2021 Inspected At:

No. 464 Macpherson Road

Singapore 368182

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$10,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT RH SIGNAL LAMP	Scratched	0.00 F	*- F
2	1	*HANDLE BAR	Bent	0.00 F	*- F
3	1	*HANDLE BAR GRIP	Cut	0.00 F	*- F
4	1	*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
5	1	*HAND BRAKE LEVER	Scratched	0.00 F	*- F
6	1	*FAIRING SHIELD RH	Scratched	0.00 F	*- F
7 F=Fra	1 anchise part.	*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*-F
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	ing this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >