

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001180/QPS3Q2-1
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100446063
Claimant Vehicle No :	SLF2956E	Insured Vehicle No :	SGL8813Y
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	3443753602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2956E		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	2NR8620481
Reg. Date:	22/08/2016 (Man. Year: 2016)	Chassis No:	NSP1707034026
Colour:	White	Odometer:	274649 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,555.50	1,134.75	420.75	27.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,100.00	1,400.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,055.50	2,234.75	1,820.75	44.90
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	4,055.50	1,800.00	2,255.50	55.62
+ GST 7.00/7.00% (S\$)	283.89	126.00	157.89	55.62
Nett Amount (S\$)	4,339.39	1,926.00	2,413.39	55.62
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
(S\$)		2,106.00		
Liabie Amount (50.00%) (S\$)		1,053.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,055.00		
Global Sum Settlement (S\$)		1,050.00		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 26/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros Centre
Singapore 737569

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING R/R DOOR,REAR BUMPER OUT TO FACILITATE REPLACEMENT OF PARTS ,ALSO REPAIR R/L FENDER	New	900.00	500.00
2	TO RESPRAY REAR BUMPER R/R DOOR AND R/R FENDER	New	1,200.00	600.00
3	TRANSFER TAILGATE MECHANISM	New	100.00	0.00
4	TO CONFIGURE KEYLESS NETWORK SECURITY SYSTEM BACK TO FACTORY SPEFICATION	New	300.00	0.00
Gross Labour Cost (\$\$)			2,500.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >