

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21009061/Vvce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER 07/09/2021 Date: SINGAPORE 068811 ATTN: TAN JUN HONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. FBM 5879G SH 8024L Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M03E5U Excess (\$) 0.00 TAN JUN HONG **Assign Date** 30/08/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA SNIPER Make & Model 150 C.C HIDDEN 2017 Engine No. Year of Reg. MH3UG0740H0067400 **BLUE** Chassis No. Colour Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 80/90-17 BRIDGESTONE 5 mm L/H Front Tyre mm 80/90-17 BRIDGESTONE R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. 5. **General Information** 21/07/2021 30/08/2021 (01:00 PM) Inspect Date / Time Accident Date 464 Macpherson Road Singapore 368182 Survey held at Repairer MOTO 51 PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

Report Ref No. CS3/ASM21009061/Vvce2

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days