

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21009064/UPA3Q2
Date: 06/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
Claimant Vehicle No :	SLX2575B	Insured Vehicle No :	SMW2313J
Date of Loss:	27/08/2021	Nature of Claim:	TP
		Claim No:	3547636994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX2575B		
Make & Model:	MAZDA 2, 1.5 SEDAN L SP.6EAT (A)	Engine No:	P520495600
Reg. Date:	21/03/2018 (Man. Year: 2017)	Chassis No:	JM6DJ2HAA01200270
Colour:	Blue	Odometer:	44377 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,954.40	2,752.40	202.00	6.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,875.00	1,505.00	370.00	19.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,829.40	4,257.40	572.00	11.84
Approved Total (Overridden) (S\$)		3,400.00		

(S\$)	4,829.40	3,400.00	1,429.40	29.60
+ GST 7.00/7.00% (S\$)	338.06	238.00	100.06	29.60
Nett Amount (S\$)	5,167.46	3,638.00	1,529.46	29.60
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,180.45		
Global Sum Settlement (S\$)		4,100.00		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 30/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

NPH Auto Service (HQ)
 Blk 9005 Tampines Steet 93, #01-246/254
 Singapore 528839

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	101.90 FL	*101.90 FL
2	1		*FRONT GRILLE CHROME MOULDING	Cracked	166.00 FL	*166.00 FL
3	1		*FRONT GRILLE CENTER LOGO	Not Necessary	33.50 FL	*- FL
4	1		*FRONT BUMPER WITH HOSE	Distorted	873.00 FL	*873.00 FL
5	8		*FRONT BUMPER CLIPS	Necessary	47.20 FL	*47.20 FL
6	1		*FRONT BUMPER AIR SCOOP GRILLE	Scratched	92.00 FL	*92.00 FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	38.00 FL	*38.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	529.00 FL	*529.00 FL
9	1		*FRONT HEADLAMP ASSY RH	Broken	580.00 FL	*580.00 FL
10	1		*FRONT HEADLAMP LOWER BUMPER RETAINER RH	No such part	42.00 FL	*- FL
11	1		*FRONT PANEL NOSE INNER GARNISH TOP	Not Necessary	98.00 FL	*- FL
12	1		*FRONT WIPER RESERVE TANK	Deformed	68.00 FL	*68.00 FL
13	1		*FRONT WIPER RESERVE TANK MOTOR	Not Necessary	79.00 FL	*- FL
14	1		*FRONT FENDER RH	Buckled	339.00 FL	*339.00 FL
15	1		*FRONT FENDER INNER COWLING RH	Torn	68.00 FL	*68.00 FL
16	8		*FRONT FENDER INNER COWLING CLIP	Necessary	38.40 FL	*38.40 FL
17	1		*FRONT RADIATOR SUPPORT PANEL FIBRE	Cracked	373.00 FL	*373.00 FL
18	1		*FRONT BUMPER SPONGE	Torn	127.00 FL	*127.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,693.00	3,440.50
- List Item Discount on L Items 20.00/20.00% (\$)	738.60	688.10
Total Parts (\$)	2,954.40	2,752.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL F/BUMPER ,F/GRILLE ,F/HEADLAMP,F/FENDER ,RADIATOR SUPPORT PANEL,KNOCK WHEEL HOUSE PANEL ,CHASSIS MEMBER AND RESTRAIGHTEN BODY & CHASSIS	New	750.00	600.00
2	SPRAY PAINTING	New	1,000.00	880.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	VACUUM & TOP UP GAS	New	100.00	0.00
Gross Labour Cost (S\$)			1,875.00	1,505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >