

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21009067/Vuce2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date:	17/09/2021	
	ATTN: CHAN KIAN	CHUAN	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 7119E	Veh. Inspected	FBJ 3411B	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03G4K	Excess (\$)	0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date	30/08/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	SYM GTS200	c.c	172	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	RFGLM18WXES002553	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	130/70-12	CITY	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130/70-12	CITY	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSPORTION.	STAINED DAMAGES AT THE O/S, N/S BODY AND FRONT			
5.	General Information				
	Accident Date	18/08/2021	Inspect Date / Time	02/09/2021 ( 10:00 AM )	
	Survey held at 10 Kaki Bukit Road 2 #01-06 First East Centre  Repairer BIKE IMAGE MOTOR TRADING				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000				
5b.					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21009067/Vuce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser