

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009068/EGA3Q2**Date:** 18/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210072109
Claimant Vehicle No :	FBP7672G	Insured Vehicle No :	SNA7914X
Date of Loss:	02/08/2021	Nature of Claim:	TP
		Claim No:	6250703855SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP7672G	Engine No:	NC42E5200084
Make & Model:	HONDA CB400, 399cc	Chassis No:	JH2NC4293KK500085
Reg. Date:	07/06/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/50 R17	Rear Tyre Size:	140/50 R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,405.50	4,872.00	1,533.50	23.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	490.00	340.00	150.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,895.50	5,212.00	1,683.50	24.41
Approved Total (Overridden) (\$\$)		4,150.00		
(\$\$)	6,895.50	4,150.00	2,745.50	39.82
+ GST 7.00/7.00% (\$\$)	482.69	290.50	192.19	39.82
Nett Amount (\$\$)	7,378.19	4,440.50	2,937.69	39.82
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	29/08/2021	
Date Inspected:	30/08/2021	Inspected At: Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 Singapore 159762
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*METER	Cut	1,680.00 FL	*1,550.00 FL
2	1		*CLUTCH LEVER	Cut	45.00 FL	*45.00 FL
3	1		*HANDLE BAR	Bent	145.00 FL	*145.00 FL
4	1		*FRONT HEAD LAMP	Bent	1,550.00 FL	*1,500.00 FL
5	1		*MIRROR	Cut	95.00 FL	*95.00 FL
6	1		*ENGINE GUARD	Dented	160.00 FL	*160.00 FL
7	1		*GEAR LEVER	Bent	140.00 FL	*90.00 FL
8	1		*FRONT FOOTREST	Missing	65.00 FL	*65.00 FL
9	1		*SET REAR FOOTREST	Cut	55.00 FL	*55.00 FL
10	1		*SET FOOTREST BRACKET	Bent	225.00 FL	*225.00 FL
11	1		*SIDE STAND	Bent	90.00 FL	*90.00 FL
12	1		*HANDLE BALANCER	Cut	35.00 FL	*35.00 FL
13	1		*FUEL TANK (LOCAL REPAIR)	Dented	1,422.00 FS	*400.00 FS
14	1		*CAM COVER (LOCAL REPAIR)	Cut	432.00 FS	*150.00 FS
15	1		*GASKET	Necessary	65.00 FL	*40.00 FL
16	1		*SIGNAL LIGHT	Cut	75.00 FL	*75.00 FL
17	1		*FORK OIL SEAL	Necessary	60.00 FL	*60.00 FL
18	1		*IU	Cut	165.00 FS	*165.00 FS
19	1		*REAR BOX	Cut	350.00 FS	*350.00 FS
					Sub Total (\$\$)	6,854.00 5,295.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	448.50 423.00
					Total Parts (\$\$)	6,405.50 4,872.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	40.00	40.00
2	ALIGNMENT FORK	New	100.00	50.00
3	LABOR	New	350.00	250.00
Gross Labour Cost (\$)			490.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >