



Your Ref : S1M03GXU

Date: 09th Sep 2021

Our Ref : CS/ASM21009070/Vuce2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Ang Yvonne

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGU 7451S
INSURED VEHICLE: SHD 3480L
ACCIDENT ON 27/08/2021

Instruction was received to inspect the vehicle Reg. No. SGU 7451S. The inspection was conducted on 30/08/2021 at the premises of M/s 68 Kaki Bukit Ave 6, #02-04/05 ARK @KB, S417896, Repairer: GFORCE Autotech Pte Ltd.

The following vehicle information was recorded:

Registration Number	: SGU 7451S
Make/Model	: Honda Fit 1.3A
Year of Registration	: 2007
Body Colour	: Black
Chassis Number	: GD12406311
Engine Capacity	: 1339 cc
Speedometer Reading	: 414188 km

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value	S\$ 5,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 3,677.00)
Nett Liability	S\$ 1,323.00 =====

Vehicle Inspected By:



Thevan Thomas Karthikesavan
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.