

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009076/GVF3N2**Date:** 08/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700034364
<b>Claimant Vehicle No :</b>	YM9008E	<b>Insured Vehicle No :</b>	SJL1575U
Date of Loss:	15/08/2021	Nature of Claim:	TP
		Claim No:	8050878305SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YM9008E</b>	Engine No:	LTA1000881
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85E87100160
Reg. Date:	03/09/2008 (Man. Year: 2008)	Odometer:	332233 km
Colour:	Blue		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205R16	Rear Tyre Size:	185R14(D)
Front Left Side:	Windforce 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	30/08/2021	
Date Inspected:	06/09/2021	Inspected At: 8 KAKI BUKIT AVE 4 #07-21 PREMIER @ KAKI BUKIT REPAIRER: ZOLAR AUTO SERVICES
Estimated Period of Repair:	3.0 days	

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$19,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*REAR END PANEL	Repair	0.00 F	*- F
3	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
5	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
6	1		*REAR EXHAUST MOUNTING	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >