



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 7778M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,358.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	2,155.00	2,155.00
1	REAR BUMPER BRACKETS RH (CONSISTENT)	NECESSARY	42.00	42.00
1	REAR SENSOR RH (CONSISTENT)	DAMAGED	165.00	165.00
1	REAR TAIL LIGHT RH (CONSISTENT)	CUT	1,050.00	1,050.00
1	REAR BUMPER LOWER SPOILER (CONSISTENT)	CUT	368.00	368.00
	LESS 5% DISCOUNT		-356.90	-
	LESS 10% DISCOUNT		-	-378.00
			6,781.10	3,402.00
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			50.00	50.00
<b>LABOUR</b>				
	TO REMOVE ,CUT OUT DAMAGE PARTS ,ALIGN ,PANEL BEATING AND RENEW REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,200.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS .		800.00	500.00
	TO REWIRE REAR PORTION.		50.00	30.00
	TO REMOVE ,FIX REVERSE SENSOR .		150.00	60.00
	TO TUFF KOTE AFFECTED AREAS .		80.00	50.00
			2,280.00	1,240.00
<b>GRAND TOTAL</b>			<b>9,111.10</b>	<b>4,692.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,700.00</b>

Report Ref No. CC4/ASM21009078/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.