

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21009081/AEA3Q2

Date:

13/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900122061

Claimant Vehicle No : SJJ6118J**Insured Vehicle No :**

SMM9806K

Date of Loss: 28/08/2021

Nature of Claim:

TP

Claim No:

6818402497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJJ6118J

Make & Model:

AUDI Q7, 2.0 TFSI QU (A)

Reg. Date:

11/08/2017 (Man. Year: 2017)

Colour:

Black

Engine Capacity:

1984 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

Engine No:

CYR033675

Chassis No:

WAUZZZ4M7HD042083

Odometer:

45730 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

255/55 R19

Rear Tyre Size:

255/55 R19

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,016.00	1,447.00	20,569.00	93.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	2,272.00	2,650.00	53.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,938.00	3,719.00	23,219.00	86.19
+ GST 7.00/7.00% (S\$)	1,885.66	260.33	1,625.33	86.19

Nett Amount (S\$)	28,823.66	3,979.33	24,844.33	86.19
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/09/2021

Date Inspected: 06/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,724.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	447.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE LH	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE END CAP -LH	Not Necessary	36.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	Not Necessary	377.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE -LOWER CENTRE	Not Necessary	206.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	807.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	210.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER -LH	Not Necessary	211.00 FS	*- FS
10	1		*FRONT BUMPER MUD GUARD -LH	Not Necessary	44.00 FS	*- FS
11	1		*FRONT BUMPER AIR GRILLE -LH	Cut	297.00 FS	*297.00 FS
12	1		*FRONT BUMPER AIR GUIDE END CAP -LH	Not Necessary	33.00 FS	*- FS
13	1		*FRONT BUMPER MUD GUARD DEFLECTOR -LH	Not Necessary	59.00 FS	*- FS
14	1		*HORN -LH	Not Necessary	226.00 FS	*- FS
15	1		*FRONT BUMPER PARKING AID -OUTER (NPA)	Not Necessary	0.00 FS	*- FS
16	4		*FRONT BUMPER PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
17	1		*HEADLIGHT MOUNTING -LH	Not Necessary	118.00 FS	*- FS
18	1		*HEADLIGHT -LH	Not Necessary	10,021.00 FS	*- FS
19	1		*HEADLIGHT LIFT CYLINDER -LH	Not Necessary	198.00 FS	*- FS
20	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	98.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	239.00 FS	*- FS
22	2		*RADIATOR AIR GUIDE -LH /LOWER	Not Necessary	71.00 FS	*- FS
23	2		*FRONT WHEEL ARCH TRIM -LH/RH	Necessary	1,150.00 FS	*1,150.00 FS
24	1		*RADIATOR GRILLE	Not Necessary	2,473.00 FS	*- FS
25	1		*RADIATOR GRILLE COVER	Not Necessary	72.00 FS	*- FS
26	1		*RADIATOR GRILLE AUDI COVER	Not Necessary	62.00 FS	*- FS
27	1		*FRONT BUMPER TOP COVER	Not Necessary	131.00 FS	*- FS
28	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
29	1		*FRONT BUMPER CARRIER FORM	Not Necessary	171.00 FS	*- FS
30	1		*FRONT BUMPER CARRIER	Not Necessary	964.00 FS	*- FS
31	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	72.00 FS	*- FS
32	1		*FROTN BUMPER GUIDE SECTION -LH	Not Necessary	44.00 FS	*- FS
33	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
34	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	22,016.00
						1,447.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
4	TO RESPRAY FRONT BUMPER ,LHS FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	2,500.00	1,000.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,922.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >