1/19/22, 9:38 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009083/VGA3Q2

**Date:** 19/01/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2000003856

Claimant Vehicle

No: SHD3679G Insured Vehicle No: SGZ3688B

Date of Loss: 29/08/2021 Nature of Claim: TP Claim No: 7161481947SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD3679G

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR941142

Reg. Date: 07/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU203533433

Colour: Blue Odometer: 634526 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm
West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,414.85	2,414.85	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	600.00	100.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,114.85	3,014.85	100.00	3.21
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	3,114.85	2,350.00	764.85	24.55
+ GST 7.00/7.00% (S\$)	218.04	164.50	53.54	24.56
Nett Amount (S\$)	3,332.89	2,514.50	818.39	24.55
+ Loss of Use (1.5 x	S\$50.00/day) (S\$)	75.00		
+ Car Rental (1.5 x S	\$125.40/day) (S\$)	188.10		
+ Doc	c/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	2,779.60		
Global Sur	m Settlement (S\$)	2,700.00		

**INSPECTION** 

Date of Assignment: 30/08/2021

Date Inspected: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Cut	499.90 FL	*499.90 FL
2	1		*SUPPORT FRONT BUMPER SIDE	Necessary	82.30 FL	*82.30 FL
3	1		*HEADLAMP ASSY LH	Cut	2,637.60 FL	*2,637.60 FL
F=Fra	ınchise	part. L=ListIten	nDisc.			
				Sub Total (S\$)	3,219.80	3,219.80
			- List Item Discount on L	. Items 25.00/25.00% (S\$)	804.95	804.95
				Total Parts (S\$)	2,414.85	2,414.85
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	PANEL BEATING	New	400.00	350.00					
2	SPRAYPAINT CHARGE	New	300.00	250.00					
		Gross Labour Cost (S\$)	700.00	600.00					
Report was unsubmitted during this print-out.									

< END OF ESTIMATES >