

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA FIT

Engine/Chassis No.: GE61155189


Date of accident:

Damaged area: Rear

Date: 07/09/2021

Claim Type: TP

VRN: SKB8188Z



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper	1	\$ 726.00	\$ 726.00
2	Rear bumper bracket	2	\$ 59.00	\$ 118.00
3	Rear bumper side retainer	2	\$ 67.00	\$ 134.00
4	Rear bumper tow hook cover	1	\$ 48.00	\$ 48.00
5	Tailgate	1	\$ 998.00	\$ 998.00
6	Tailgate "FIT" emblem	1	\$ 48.00	\$ 48.00
7	Tailgate "HONDA" Logo	1	\$ 36.00	\$ 36.00
8	Tailgate inner trimboard	1	\$ 496.00	\$ 496.00
9	Tailgate outer garnish	1	\$ 238.00	\$ 238.00
10	Tailgate outer handle	1	\$ 98.00	\$ 98.00
11	Tailgate lock	1	\$ 287.00	\$ 287.00
12	Tailgate lock striker	1	\$ 68.00	\$ 68.00
13	End panel	1	\$ 665.00	\$ 665.00
14	End panel top garnish	1	\$ 213.00	\$ 213.00
15	Taillamp	2	\$ 576.00	\$ 1,152.00
16	Taillamp lower bracket	2	\$ 33.00	\$ 66.00
17	Rear number plate lamp	2	\$ 58.00	\$ 116.00
18	Rear wheel panel tool box	1	\$ 238.00	\$ 238.00
19	Rear wheel panel trimboard	1	\$ 296.00	\$ 296.00
20	Windscreen moulding	1	\$ 182.00	\$ 182.00
21	Tailgate weatherstrip	1	\$ 189.00	\$ 189.00
22	Exhaust assy	1	\$ 937.00	\$ 937.00
23	Exhaust assy heatshield	1	\$ 132.00	\$ 132.00
24	Exhaust assy holder	2	\$ 38.00	\$ 76.00
			<b>Subtotal</b>	<b>\$ 7,557.00</b>
			<b>List discount</b>	<b>20.00%</b>
			<b>Total</b>	<b>\$ 6,045.60</b>

# Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips	8	\$ 5.50	\$ 44.00
2	End panel inner garnish clip	6	\$ 5.50	\$ 33.00
3	End panel top garnish clips	6	\$ 5.50	\$ 33.00
4	Tailgate inner trimboard clips	8	\$ 5.50	\$ 44.00
5	Reverse sensors	1	\$ 280.00	\$ 280.00
6	Rear number plate & frame	1	\$ 55.00	\$ 55.00
7	End panel sealant	1	\$ 120.00	\$ 120.00
8	Rear windscreen sealant	1	\$ 120.00	\$ 120.00
9	Rear bumper lower skirting	1	\$ 650.00	\$ 650.00
10	Rear bumper chrome exhaust garnish	2	\$ 180.00	\$ 360.00
11	Rear bumper lower skirting sealant	1	\$ 100.00	\$ 100.00
12	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,889.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test distance and functions.	0.25	\$ 50.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,050.00

Estimate Grand Total	\$ 10,984.60
----------------------	--------------