

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Authorized
11 Sep @ 4000h
Presurvey After Paint
6 days

Make/Model: HONDA FIT
Engine/Chassis No.: GE61155189
Date of accident:
Damaged area: Rear

Date: 07/09/2021
Claim Type: TP
VRN: SKB8188Z



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper 4P7.20	1	\$ 726.00	\$ 726.00	✓
2	Rear bumper bracket	2	\$ 59.00	\$ 118.00	X
3	Rear bumper side retainer	2	\$ 67.00	\$ 134.00	✓
4	Rear bumper tow hook cover	1	\$ 48.00	\$ 48.00	✓
5	Tailgate 771.20	1	\$ 998.00	\$ 998.00	✓
6	Tailgate "FIT" emblem	1	\$ 48.00	\$ 48.00	✓
7	Tailgate "HONDA" Logo	1	\$ 36.00	\$ 36.00	X
8	Tailgate inner trimboard	1	\$ 496.00	\$ 496.00	X
9	Tailgate outer garnish	1	\$ 238.00	\$ 238.00	X
10	Tailgate outer handle	1	\$ 98.00	\$ 98.00	X
11	Tailgate lock 186.20	1	\$ 287.00	\$ 287.00	✓
12	Tailgate lock striker	1	\$ 68.00	\$ 68.00	X
13	End panel 276.50	1	\$ 665.00	\$ 665.00	✓
14	End panel top garnish 140.20	1	\$ 213.00	\$ 213.00	✓
15	Taillamp e 206.20	2	\$ 576.00	\$ 1,152.00	✓
16	Taillamp lower bracket	2	\$ 33.00	\$ 66.00	X
17	Rear number plate lamp	2	\$ 58.00	\$ 116.00	X
18	Rear wheel panel tool box	1	\$ 238.00	\$ 238.00	X
19	Rear wheel panel trimboard	1	\$ 296.00	\$ 296.00	X
20	Windscreen moulding 60	1	\$ 182.00	\$ 182.00	✓
21	Tailgate weatherstrip 165	1	\$ 189.00	\$ 189.00	508 in 82.50 in
22	Exhaust assy 446.80	1	\$ 937.00	\$ 937.00	✓
23	Exhaust assy heatshield	1	\$ 132.00	\$ 132.00	X
24	Exhaust assy holder	2	\$ 38.00	\$ 76.00	X
Subtotal				\$ 7,557.00	
List discount				20.00%	
Total				\$ 6,045.60	

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips	8	\$ 5.50	\$ 44.00
2	End panel inner garnish clip	6	\$ 5.50	\$ 33.00
3	End panel top garnish clips	6	\$ 5.50	\$ 33.00
4	Tailgate inner trimboard clips	8	\$ 5.50	\$ 44.00
5	Reverse sensors	1	\$ 280.00	\$ 280.00
6	Rear number plate & frame	1	\$ 55.00	\$ 55.00
7	End panel sealant	1	\$ 120.00	\$ 120.00
8	Rear windscreen sealant	1	\$ 120.00	\$ 120.00
9	Rear bumper lower skirting	1	\$ 650.00	\$ 650.00
10	Rear bumper chrome exhaust garnish	2	\$ 180.00	\$ 360.00
11	Rear bumper lower skirting sealant	1	\$ 100.00	\$ 100.00
12	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,889.00

✓
✓
X
X
2005n
X
305n
405n
✓
X
305n
X

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test distance and functions.	0.25	\$ 50.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,050.00

600l
20l
60l
✓
120l
800l
60l

Estimate Grand Total	\$ 10,984.60
----------------------	--------------

LKK Auto hereby notify
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

LKK Auto Consultants hence notify
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: