

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20011243/GVF3E2-1

Date: 06/10/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant Vehicle No : FBP8999H

Insured Vehicle No : SLP9053L

Date of Loss: 15/10/2020

Nature of Claim:

TP

Claim No: 629924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP8999H**

Make & Model: HONDA NSS 300A, 279cc

Engine No: NF07E2016769

Reg. Date: 31/07/2019 (Man. Year: 2019)

Chassis No: MLHNF0798J5000564

Colour: White

Odometer: 23799 km

Engine Capacity: 279 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Rear Tyre Size: 140/70-14

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,168.11	1,934.25	1,233.86	38.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	600.00	990.00	62.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,758.11	2,534.25	2,223.86	46.74
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,758.11	2,000.00	2,758.11	57.97
+ GST 7.00/7.00% (S\$)	333.07	140.00	193.07	57.97
Nett Amount (S\$)	5,091.18	2,140.00	2,951.18	57.97

INSPECTION

Date of Assignment: 16/10/2020

Date Inspected: 16/10/2020 Inspected At:

149 Kaki Bukit Ave 1 Soon Lee Industrial Park

Singapore 416009

Repairer: Garage 13 Pte. Ltd.

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Oct 2021)	
Parts:	N/A	HONDA NSS 300A 279cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP8999H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SIDE FRAME COVER LH	Damaged	225.00 FL	*225.00 FL
2	1		*LEFT SIDE FRAME COVER INNER LH	Damaged	188.00 FL	*153.00 FL
3	1		*LOWER COVER SET LH	Damaged	215.00 FL	*215.00 FL
4	1		*HANDLE BAR	Damaged	155.00 FL	*155.00 FL
5	1		*AIR FILTER COVER	Damaged	142.00 FL	*142.00 FL
6	1		*FORK ASSY	Serviceable	785.00 FL	*- FL
7	1		*SIDE MIRROR LH	Damaged	150.00 FL	*150.00 FL
8	1		*SET BALANCER	Damaged	114.00 FL	*37.00 FL
9	1		*BRAKE LEVER	Damaged	95.00 FL	*47.00 FL
10	1		*FOOT REST GARNISH TOP	Damaged	85.00 FL	*85.00 FL
11	1		*FOOT REST GARNISH CENTER	Damaged	85.00 FL	*85.00 FL
12	1		*FOOT REST GARNISH LOWER	Damaged	79.00 FL	*79.00 FL
13	1		*FRONT MUDGUARD	Damaged	158.90 FL	*127.00 FL
14	1		*DOUBLE STAND	Damaged	135.00 FL	*105.00 FL
15	1		*V-BELT COVER	Damaged	200.00 FL	*200.00 FL
16	1		*SPORT RIM (FRONT)	Damaged	598.00 FS	*250.00 FS
17	1		*BOX	Damaged	180.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,589.90	2,205.00
- List Item Discount on L Items 15.00/15.00% (\$)	421.79	270.75
Total Parts (\$)	3,168.11	1,934.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	500.00	200.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS.JOB ALLOWANCE.PAINT/MATERIAL (WHOLE BODY)	New	700.00	400.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	20.00	0.00
4	FRONT WHEEL ALIGNMENT CHARGES/BODY CHASSIS ALIGNMENT CHARGES	New	350.00	0.00
5	WIRING AND BULB CHECKING	New	20.00	0.00
Gross Labour Cost (\$\$)			1,590.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >