

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21009088/T1uce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 07/09/2021 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 4093E GBD 1571S Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03GLX Excess (\$) 0.00 **LOH CYNTHIA Assign Date** 30/08/2021 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA DYNA 150** Make & Model 2982 C.C HIDDEN 2014 Engine No. Year of Reg. JTFAT35YX0K203078 SILVER Chassis No. Colour Odometer 123492 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/75 R15 LINAM 6 mm L/H Front Tyre 195/75 R15 LINAM 6 mm 155 R12 (D) LINAM R/H Rear Tyre 6/6 mm LINAM L/H Rear Tyre 155 R12 (D) 6/6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 26/08/2021 31/08/2021 (05:45 PM) Inspect Date / Time Accident Date **H S AUTOMOTIVE SERVICES** Survey held at 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$6,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM21009088/T1uce2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days

Automotive Assessor