

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/GRB21009092/R1GS3Q2

Date:

18/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0006849

Claimant Vehicle No : SJU2418L**Insured Vehicle No :**

SMA6930S

Date of Loss: 30/08/2021

Nature of Claim:

TP

Claim No:

MFL2021D0003686

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJU2418L**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No:

G4FC9U754353

Reg. Date: 25/11/2009 (Man. Year: 2009)

Chassis No:

KMHU41BMAU902450

Colour: Maroon

Odometer:

199644 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,930.00	1,675.00	6,255.00	78.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,590.00	620.00	28.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,140.00	3,265.00	6,875.00	67.80
Approved Total (Overridden) (S\$)		2,600.00		

(S\$)	10,140.00	2,600.00	7,540.00	74.36
+ GST 7.00/7.00% (S\$)	709.80	182.00	527.80	74.36
Nett Amount (S\$)	10,849.80	2,782.00	8,067.80	74.36
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,217.45		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 30/08/2021

Estimated Period of Repair: 7.0 days

Inspected At:

48 TOH GUAN RD EAST #02-146/147

Repairer:Automotive Repair Centre Pte Ltd (HQ)

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU2418L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	650.00 F	*650.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	50.00 F	*- FL
4	1		*FRONT BUMPER RETAINER LH	Serviceable	50.00 F	*- FL
5	1		*FRONT REINFORCEMENT	Serviceable	350.00 F	*- FL
6	1		*FRONT SPONGE	Serviceable	120.00 F	*- FL
7	1		*FRONT GRILLE ASSY	Serviceable	380.00 F	*- FL
8	1		*FRONT LOWER GRILLE (CENTER)	Serviceable	200.00 F	*- FL
9	1		*FRONT SUPPORT PANEL	Serviceable	620.00 F	*- FL
10	1		*FOGLAMP GARNISH RH	Serviceable	40.00 F	*- FL
11	1		*FOGLAMP GARNISH LH	Serviceable	40.00 F	*- FL
12	1		*HEADLAMP RH	Serviceable	350.00 F	*- FL
13	1		*HEADLAMP LH	Serviceable	350.00 F	*- FL
14	1		*REAR BUMPER	Deformed	680.00 F	*680.00 FL
15	10		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
16	1		*REAR BUMPER RETAINER RH	Cracked	50.00 F	*50.00 FL
17	1		*REAR BUMPER RETAINER LH	Serviceable	50.00 F	*- FL
18	1		*REAR REINFORCEMENT	Cracked	380.00 F	*380.00 FL
19	1		*REAR SPONGE	Cracked	130.00 F	*130.00 FL
20	1		*REAR TAIL LAMP RH	Serviceable	280.00 F	*- FL
21	1		*REAR BOOTLID LAMP RH	Serviceable	230.00 F	*- FL
22	1		*REAR BOOTLID	Repair	1,150.00 F	*- FL
23	1		*REAR BOOTLID LOCK	Serviceable	120.00 F	*- FL
24	1		*REAR BOOTLID RUBBER SEAL	Serviceable	80.00 F	*- FL
25	1		*REAR BOOTLID OUTER CHROME GARNISH	Serviceable	80.00 F	*- FL
26	1		*REAR HYUNDAI EMBLEM	Necessary	50.00 F	*50.00 FL
27	1		*REAR AVANTE EMBLEM	Necessary	50.00 F	*50.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*END PANEL	Repair	550.00 F	*- FL
29	1		*END PANEL GARNISH	Serviceable	60.00 F	*- FL
30	1		*ENGINE MOUNT RH	Serviceable	250.00 F	*- FL
31	1		*FRONT LICENSE PLATE WITH CASING	Bent	40.00 FS	*35.00 FS
32	1		*REAR LICENSE PLATE WITH CASING	Serviceable	40.00 FS	*- FS
33	2		*REVERSE SENSOR	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,930.00	2,085.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	410.00
Total Parts (\$)	7,930.00	1,675.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT (FRONT BUMPER ,BONNET ,REAR BUMPER & BOOTLID)	New	1,000.00	800.00
2	REMOVE AND REFIT AFFECTED ACCIDENT AREA	New	1,000.00	700.00
3	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	New	80.00	60.00
4	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL	New	100.00	0.00
5	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			2,210.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >