

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM21009093/R1vce2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	02/09/2021	
	ATTN: LOH CYNTH	HIA	Code	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7500S	Veh. Inspected	FBL 9648K	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S1M03GLT	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	30/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB 400	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	JH2NC4297BK300245	Colour	MULTI COLOUR	
	Odometer	153594 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60ZR17	PIRELLI	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60ZR17	PIRELLI	4 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUS BODY.	STAINED DAMAGES AT THE REA			
5.	5. General Information				
	Accident Date	25/08/2021	Inspect Date / Time	31/08/2021 (12:35 PM)	
	Survey held at YONG SENG HENG MOTOR SERVICES				
	NO. 5 SOON LEE STREET #01-12 PIONEER POINT SINGAPORE 627607				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21009093/R1vce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD Auto Computer OF Liverage Association

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$