

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21009098/VUF3E2

Date: 10/09/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000194		
Claimant Vehicle No :	SHD3311S	Insured Vehicle No :	SLQ3310D		
Date of Loss:	29/08/2021	Nature of Claim:	TP	Claim No:	M2104001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3311S	Engine No:	D4FDGU706883
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU093155
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	580175 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,630.02	1,930.82	2,699.20	58.30
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,330.00	1,110.00	220.00	16.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,971.02	3,051.82	2,919.20	48.89
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	5,971.02	2,400.00	3,571.02	59.81
+ GST 7.00/7.00% (S\$)	417.97	168.00	249.97	59.81
Nett Amount (S\$)	6,388.99	2,568.00	3,820.99	59.81

INSPECTION

Date of Assignment:	30/08/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/08/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3311S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Cut	1,106.00 FL	-	*1,106.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER SPONGE	Repair	119.50 FL	-	*- FL
4	1		*REAR BUMPER REINFORCEMENT BEAM	Repair	428.40 FL	-	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Repair	160.60 FL	-	*- FL
6	1		*REAR BUMPER SIDE BRACKET RH	Necessary	35.60 FL	-	*35.60 FL
7	1		*REAR BUMPER UNDER COVER	Cut	288.00 FL	-	*288.00 FL
8	1		*REAR BUMPER REFLECTOR RH	Cracked	32.00 FL	-	*32.00 FL
9	1		*REAR EXHAUST PIPE RH	Repair	1,935.40 FL	-	*- FL
10	1		*REAR EXHAUST PIPE CENTRE	Repair	730.10 FL	-	*- FL
11	1		*TAILLAMP ASSY RH	Cracked	697.80 FL	-	*697.80 FL
12	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	-	*50.00 F
13	1		*REVERSE SENSOR	Cut	135.70 F	-	*135.70 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,741.10	2,367.10
- List Item Discount on L Items 20.00/20.00% (S\$)	1,111.08	436.28
Total Parts (S\$)	4,630.02	1,930.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	560.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			1,330.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >